

Equipment ID: OTRT W24403 VIN: 1JUV532DXHL026261 Year: 2017 Manufacturer: WABASH Primary Plate: ME 403146Z

**XTRA Lease DOT / BIT Inspection and PM Worksheet**  
 Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

- Glad Hands & Rubber Grommets  Repaired
- 7-Way Electrical Plug  Repaired
- Registration, Valid License Plate and sticker  Repaired
- Lights, Wiring and Splice Conditions  Repaired
- Exterior Trailer - Body Condition and Coupling Device  Repaired
- Corner Locking Devices  Repaired
- Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle  Repaired
- Fuel Tank and Fuel System (Reefer)  Repaired
- Air Brake System - Test for Leaks  Repaired
- Dump Valve (Air Ride Only) - Test operation and check for Leaks  Repaired
- ABS System - Actuate  Repaired
- Air Lines - Check for damage / wear / chaffing  Repaired
- Suspension Hangers  Repaired
- Air Tank and Mounting Brackets  Repaired
- Brakes - Drums / Linings / Air Chambers  Repaired
- Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads  Repaired
- Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust  Repaired
- Suspension / U-Bolts / Springs  Repaired
- Flatted Winches - Lubricate and Cycle  Repaired

**TIRES (in 32nds)**

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	6	Good Year	100	RO Front	10	Good Year	100
	LI Front	6	Bridge Stone	100	RI Front	8	Good Year	100
2	LO Middle	N/A	N/A	N/A	RO Middle	N/A	N/A	N/A
	LI Middle	N/A	N/A	N/A	RI Middle	N/A	N/A	N/A
3	LO Rear	9	Bridge Stone	100	RO Rear	11	Goodyear	100
	LI Rear	11	Bridge Stone	100	RI Rear	11	Goodyear	100

**Brakes (Drum in 8ths / ADB in mm)**

Axle	Position	Depth	Hub:
1	L Front	4	2859d
	R Front	4	
2	L Middle	N/A	Engine Hrs: _____
	R Middle	N/A	Prot. Time: _____
3	L Rear	6	Fuel 8ths: _____
	R Rear	6	

- NOTES:**
- Sub-Frame - Slide Rails and Crossmembers  Repaired
  - Aerodynamic Side Skirts  Repaired
  - Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage  Repaired
  - Proper Lubricant Level in each Wheel End - Fill if necessary  Repaired
  - Wheels - Check for Cracks / Tire Matching  Repaired
  - Tires - free of impermissible damage or wear  Repaired
  - Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs  Repaired
  - Metal Flow-Thru Valve Stem Caps  Repaired
  - Metal Flow-Thru Valve Stem Caps  Repaired
  - Conspicuity Tape-Side Panels, Rear Doors, Headboards  Repaired
  - Mudflaps, Brackets, and Rubber Dock Bumpers  Repaired
  - Rear Impact Guard  Repaired
  - Doors - Proper Operation  Repaired
  - Door Hold Backs and Pull Handles - Present & Functional  Repaired
  - All Hinges, Rollers, Locks - Lubricate  Repaired
  - Interior Trailer - Floor, Roof, and Side Walls  Repaired
  - Interior - Resecure Plywood as Needed  Repaired
  - DOT Inspected - Sticker Applied  Repaired
  - California BIT Inspected & Passed  Repaired

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: [Signature] (Inspector signature)

Inspection Date: 9-1-2013

Print Name: Danilton Hunt

Company Name: XTRA Lease LLC