

Equipment ID  
H12166

VIN  
3H3V532K4SS134127

Year  
2025

Manufacturer  
HYUNDAI

Primary Plate  
ME 5375045

### XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

- Glad Hands & Rubber Grommets
- 7-Way Electrical Plug
- Registration, Valid License Plate and sticker
- Lights, Wiring and Splice Conditions
- Exterior Trailer - Body Condition and Coupling Device
- N/A Corner Locking Devices
- Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle
- N/A Fuel Tank and Fuel System (Reefer)
- Air Brake System - Test for Leaks
- Dump Valve (Air Ride Only) - Test operation and check for Leaks
- ABS System - Actuate
- Air Lines - Check for damage / wear / chaffing
- Suspension Hangers
- Air Tank and Mounting Brackets
- Brakes - Drums / Linings / Air Chambers
- Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads
- Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust
- Suspension / U-Bolts / Springs
- N/A Flatbed Winches - Lubricate and Cycle

- Repaired   Sub-Frame - Slide Rails and Crossmembers
- Repaired   Aerodynamic Side Skirts
- Repaired   Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage
- Repaired   Proper Lubricant Level in each Wheel End - Fill if necessary
- Repaired   Wheels - Check for Cracks / Tire Matching
- Repaired   Tires - free of impermissible damage or wear
- Repaired   Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs
- Repaired   Metal Flow-Thru Valve Stem Caps
- Repaired   Conspicuity Tape - Side Panels, Rear Doors, Rear Impact Guard, Headboards
- Repaired   Mudflaps, Brackets, Rubber Dock Bumpers, and Rear Impact Guard
- Repaired   Doors - Proper Operation
- Repaired   Door Hold Backs and Pull Handles - Present & Functional
- Repaired   All Hinges, Rollers, Locks - Lubricate
- Repaired   Interior Trailer - Floor, Roof, and Side Walls
- Repaired   Interior - Resecure Plywood as Needed
- Repaired   DOT Inspected - Sticker Applied
- Repaired   California BIT Inspected & Passed
- Repaired  NOTES:

#### TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	11	YOKOHAMA	100	RO Front	11	YOKOHAMA	100
	LI Front	11	YOKOHAMA	100	RI Front	11	YOKOHAMA	100
2	LO Middle	N/A	N/A	N/A	RO Middle	N/A	N/A	N/A
	LI Middle	N/A	N/A	N/A	RI Middle	N/A	N/A	N/A
3	LO Rear	11	YOKOHAMA	100	RO Rear	11	YOKOHAMA	100
	LI Rear	11	YOKOHAMA	100	RI Rear	11	YOKOHAMA	100

#### Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	7/8"
	R Front	7/8"
2	L Middle	N/A
	R Middle	N/A
3	L Rear	7/8"
	R Rear	7/8"

Hubo: 13,302

Engine Hrs: N/A

Prot. Time: \_\_\_\_\_

Fuel 8ths: \_\_\_\_\_

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: Timothy Keating  
(Inspector signature)

Inspection Date: 05/05/25

Print Name: TIMOTHY KEATING

Company Name: KC TRAILER PROZ