

Equipment ID: OTRT H15791 VIN: 1JJV532D5TL661218 Year: 2026 Manufacturer: WABASH Primary Plate: ME 5459392

XTRA Lease DOT /BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

- Glad Hands & Rubber Grommets Repaired
- 2-Way Electrical Plug Repaired
- Registration, Valid License Plate and sticker Repaired
- Lights, Wiring and Splice Conditions Repaired
- Exterior Trailer - Body Condition and Coupling Device Repaired
- Corner Locking Devices Repaired
- Landing Gear Legs Gear Box and Bracing - Lubricate & Cycle Repaired
- Fuel Tank and Fuel System (Reeler) Repaired
- Air Brake System - Test for Leaks Repaired
- Dump Valve (Air Ride Only) - Test operation and check for Leaks Repaired
- ABS System - Actuate Repaired
- Air Lines - Check for damage /wear /chaffing Repaired
- Suspension Hangers Repaired
- Air Tank and Mounting Brackets Repaired
- Brakes - Drums/Linings /Air Chambers Repaired
- Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads Repaired
- Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust Repaired
- Suspension / U-Bolts / Springs Repaired
- Flatbed Winches - Lubricate and Cycle Repaired

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	11/32	67	100	RO Front	11/32	67	100
	LI Front	11/32	67	100	RI Front	11/32	67	100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	11/32	67	100	RO Rear	11/32	67	100
	LI Rear	11/32	67	100	RI Rear	11/32	67	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	6/8
	R Front	6/8
2	L Middle	
	R Middle	
3	L Rear	6/8
	R Rear	6/8

- Sub-Frame - Slide Rails and Crossmembers Repaired
- Aerodynamic Side Skirts Repaired
- Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage Repaired
- Proper Lubricant Level in each Wheel End - Fill if necessary Repaired
- Wheels - Check for Cracks / Tire Matching Repaired
- Tires - free of impermissible damage or wear Repaired
- Lugnuts - Torque to 450 -500 ft/lbs - Set wrench to 500 ft/lbs Repaired
- Metal Flow-Thru Valve Stem Caps Repaired
- Conspicuity Tape - Side Panels, Rear Doors, Headboards Repaired
- Mudflaps, Brackets, and Rubber Dock Bumpers Repaired
- Rear Impact Guard Repaired
- Doors - Proper Operation Repaired
- Door Hold Backs and Pull Handles - Present & Functional Repaired
- All Hinges, Rollers, Locks - Lubricate Repaired
- Interior Trailer - Floor, Roof, and Side Walls Repaired
- Interior - Resecure Plywood as Needed Repaired
- DOT Inspected - Sticker Applied Repaired
- California BIT Inspected & Passed Repaired

By signing and dating this form the inspector certifies: (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: [Signature] (Inspector signature)
 Print Name: Daulton Huff

Inspection Date: 4-23-2026
 Company Name: XTRA Lease LLC

Hubo: 15568

Engine Hrs: _____
 Prot. Time: _____
 Fuel 8ths: _____