

Equipment ID: OTRT W33430
 VIN: 3H3V532C3J1277779
 Year: 2018
 Manufacturer: HYUNDAI
 Primary Plate: ME 418591Z

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

- Glad Hands & Rubber Grommets Repaired
- 7-Way Electrical Plug Repaired
- Registration, Valid License Plate and sticker Repaired
- Lights, Wiring and Splice Conditions Repaired
- Exterior Trailer - Body Condition and Coupling Device Repaired
- Corner Locking Devices Repaired
- Landing Gear Legs / Gear Box and Bracing - Lubricate & Cycle Repaired
- Fuel Tank and Fuel System (Reefer) Repaired
- Air Brake System - Test for Leaks Repaired
- Dump Valve (Air Ride Only) - Test/operation and check for Leaks Repaired
- ABS System - Actuate Repaired
- Air Lines - Check for damage / wear / chaffing Repaired
- Suspension Hangers Repaired
- Air Tank and Mounting Brackets Repaired
- Brakes - Drums / Linings / Air Chambers Repaired
- Brakes - ADB / Rotors, Calipers, Pistons, Chambers, Pads Repaired
- Slack Adjusters / S-cams / Brake adjustment - Lubricate & adjust Repaired
- Suspension / U-Bolts / Springs Repaired
- Flatbed Winches - Lubricate and Cycle Repaired

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	GOOD YEAR	100	RO Front	6	BRIDGESTONE	100
	LI Front	10	GOOD YEAR	100	RI Front	7	BRIDGESTONE	100
2	LO Middle				RO Middle			
	LI Middle	12	DUNLOP	100	RI Middle	10	DUNLOP	100
3	LO Rear				RO Rear			
	LI Rear	12	DUNLOP	100	RI Rear	10	DUNLOP	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth	Hub:
1	L Front	6	A/B Hub
	R Front	6	
2	L Middle		
	R Middle		
3	L Rear	6	
	R Rear	6	

NOTES:

- Proper Lubricant Level in each Wheel End - Fill if necessary Repaired
- Wheels - Check for Cracks / Tire Matching Repaired
- Tires - free of impermissible damage or wear Repaired
- Lugnuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs Repaired
- Metal Flow-Thru Valve Stem Caps Repaired
- Conspicuity Tape-Side Panels, Rear Doors, Headboards Repaired
- Mudflaps, Brackets, and Rubber Dock Bumpers Repaired
- Rear Impact Guard Repaired
- Doors - Proper Operation Repaired
- Door Hold Backs and Pull Handles - Present & Functional Repaired
- All Hinges, Rollers, Locks - Lubricate Repaired
- Interior Trailer - Floor, Roof, and Side Walls Repaired
- Interior - Resecure Plywood as Needed Repaired
- DOT Inspected - Sticker Applied Repaired
- California BIT Inspected & Passed Repaired

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: [Signature]
 (Inspector signature)

Inspection Date: 5-18-23

Print Name: David McClary

Company Name: KANSAS CITY TRAILER PROZ LLC