Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT W81472	1JJV532D9KL157849	2019	WABASH	ME 428398Y

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

☑	Glad Hands & Rubber Grommets	Repaired	☑	Sub-Frame – Slide Rails and Crossmembers
☑	7-Way Electrical Plug	Repaired	☑	Aerodynamic Side Skirts
☑	Registration, Valid License Plate and sticker	Repaired	☑	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage
☑	Lights, Wiring and Splice Conditions	Repaired	☑	Proper Lubricant Level in each Wheel End - Fill if necessary
☑	Exterior Trailer - Body Condition and Coupling Device	Repaired	☑	Wheels - Check for Cracks / Tire Matching
☑	Corner Locking Devices	Repaired	☑	Tires - free of impermissible damage or wear
☑	Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle	Repaired	☑	Lugnuts – Torque to 450-500 ft/lbs – Set wrench to 500 ft/lbs
N/A	Fuel Tank and Fuel System (Reefer)	Repaired	☑	Metal Flow-Thru Valve Stem Caps
☑	Air Brake System - Test for Leaks	Repaired	☑	Conspicuity Tape–Side Panels, Rear Doors, Headboards
N/A	Dump Valve (Air Ride Only) - Testoperation and check for Leaks	Repaired	☑	Mudflaps, Brackets, and Rubber Dock Bumpers
☑	ABS System - Actuate	Repaired	☑	Rear Impact Guard
☑	Air Lines - Check for damage / wear / chaffing	Repaired	☑	Doors – Proper Operation
☑	Suspension Hangers	Repaired	☑	Door Hold Backs and Pull Handles - Present & Functional
☑	Air Tank and Mounting Brackets	Repaired	☑	All Hinges, Rollers, Locks – Lubricate
N/A	Brakes - Drums / Linings /Air Chambers	Repaired	☑	Interior Trailer – Floor, Roof, and Side Walls
☑	Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads	Repaired	☑	Interior – Resecure Plywood as Needed
☑	Slack Adjusters / S-cams / Brake adjustment – Lubricate & adjust	Repaired	☑	DOT Inspected – Sticker Applied
☑	Suspension / U-Bolts / Springs	Repaired	N/A	California BIT Inspected & Passed
N/A	Flatbed Winches – Lubricate and Cycle	Repaired	☐	NOTES:

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	8	Bridgestone	100	RO Front	8	Bridgestone	100
	LI Front	8	Bridgestone	100	RI Front	8	Bridgestone	100
2	LO Middle	N/A	N/A		RO Middle	N/A	N/A	
	LI Middle				RI Middle			
3	LO Rear	10	Bridgestone	100	RO Rear	6	Bridgestone	100
	LI Rear	11	Bridgestone	100	RI Rear	6	Bridgestone	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	17
	R Front	17
2	L Middle	N/A
	R Middle	
3	L Rear	18
	R Rear	18

Hubo: 96231

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: Paul A (Inspector signature)

Inspection Date: 10-20-2023

Print Name: Paul Ion Hunt

Company Name: XTRA Lease LLC