

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
12923	53166
DATE 12/09/23	

MOTOR CARRIER OPERATOR ICD Freight INC	INSPECTOR'S NAME (PRINT OR TYPE) Kiran Singh
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Lenexa, KS	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER 4PL410423
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) City Truck Hire

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM											
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			12. WINDSHIELD GLAZING
✓			b. Parking Brake System	✓			b. Front End Structure	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			13. WINDSHIELD WIPERS
✓			d. Brake Hose	✓				✓			No missing, damaged, or inoperable wipers.
✓			e. Brake Tubing	✓				✓			14. MOTORCOACH SEATS
✓			f. Low Pressure Warning Device	✓				✓			Seats securely fastened to the vehicle structure.
✓			g. Tractor Protection Valve	✓				✓			15. REAR IMPACT GUARD
✓			h. Air Compressor	✓				✓			In place, securely attached, proper size, proper placement (see 393.86).
✓			i. Electric Brakes	✓				✓			16. OTHER
✓			j. Hydraulic Brakes	✓				✓			List any other condition(s) which may prevent safe operation of this vehicle.
✓			k. Vacuum Systems	✓				✓			
✓			l. Antilock Brake System	✓				✓			
✓			m. Automatic Brake Adjusters	✓				✓			
2. COUPLING DEVICES											
✓			a. Fifth Wheels	✓				✓			
✓			b. Pintle Hooks	✓				✓			
✓			c. Drawbar/Towbar Eye	✓				✓			
✓			d. Drawbar/Towbar Tongue	✓				✓			
✓			e. Safety Devices	✓				✓			
✓			f. Saddle-Mounts	✓				✓			
3. EXHAUST SYSTEM											
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓				✓			
✓			b. Bus: No leaking/ discharging in violation of standard.	✓				✓			
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓				✓			
4. FUEL SYSTEM											
✓			a. No visible leak.	✓				✓			
✓			b. Fuel Tank Filler Cap	✓				✓			
✓			c. Fuel tank securely attached.	✓				✓			
5. LIGHTING DEVICES											
✓			All required lights/reflectors operable.	✓				✓			
6. SAFE LOADING											
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓				✓			
✓			b. Front End Structure	✓				✓			
✓			c. Intermodal Container Securement Devices	✓				✓			
7. STEERING MECHANISM											
✓			a. Steering Wheel Free Play	✓				✓			
✓			b. Steering Column	✓				✓			
✓			c. Front Axle Beam/All Other Steering Components	✓				✓			
✓			d. Steering Gear Box	✓				✓			
✓			e. Pitman Arm	✓				✓			
✓			f. Power Steering	✓				✓			
✓			g. Ball and Socket Joints	✓				✓			
✓			h. Tie Rods and Drag Links	✓				✓			
✓			i. Nuts	✓				✓			
✓			j. Steering System	✓				✓			
8. SUSPENSION											
✓			a. Axle Positioning Parts	✓				✓			
✓			b. Spring Assembly	✓				✓			
✓			c. Torque, Radius or Tracking Components	✓				✓			
9. FRAME											
✓			a. Frame Members	✓				✓			
✓			b. Tire and Wheel Clearance	✓				✓			
✓			c. Adjustable Axle Assemblies (Sliding Subframes)	✓				✓			
10. TIRES											
✓			a. Steer-Axle Tires	✓				✓			
✓			b. All Other Tires	✓				✓			
✓			c. Speed-Restricted Tires	✓				✓			
11. WHEELS AND RIMS											
✓			a. Lock or Side Ring	✓				✓			
✓			b. Wheels and Rims	✓				✓			
✓			c. Fasteners	✓				✓			
✓			d. Welds	✓				✓			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: OK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.