

Equipment ID: OTRT W35768
 VIN: 3H3V532C4KT472274
 Year: 2019
 Manufacturer: HYUNDAI
 Primary Plate: ME 282908X

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

<input checked="" type="checkbox"/>	Blade Hands & Rubber Grommets	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Sub-Frame - Slide Rails and Crossmembers	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	7-Way Electrical Plug	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Aerodynamic Side Skirts	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Registration, Valid License Plate and sticker	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Lights, Wiring and Splice Conditions	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Proper Lubricant Level in each Wheel End - Fill if necessary	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Exterior Trailer - Body Condition and Coupling Device	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Wheels - Check for Cracks / Tire Matching	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Corner Locking Devices	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Tires - free of impermissible damage or wear	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Landing Gear Legs (Gear Box and Bracing - Lubricate & Cycle	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Nuts - Torque to 450-500 ft/lbs - Set wrench to 500 ft/lbs	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Fuel Tank and Fuel System (Reefer)	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Metal Flow-Thru Valve Stem Caps	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Air Brake System - Test for Leaks	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Conspicuity Tape-Side Panels, Rear Doors, Headboards	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Dump Valve (Air Ride Only) - Test operation and check for Leaks	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Mudflaps, Brackets, and Rubber Dock Bumpers	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	ABS System - Actuate	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Rear Impact Guard	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Air Lines - Check for damage / wear / chaffing	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Doors - Proper Operation	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Suspension Hangers	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Door Hold Backs and Pull Handles - Present & Functional	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Air Tank and Mounting Brackets	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	AK Hinges, Rollers, Locks - Lubricate	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Brakes - Drums / Linings / Air Chambers	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Interior Trailer - Floor, Roof, and Side Walls	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Brakes - ADB / Rotors, Callipers, Pistons, Chambers, Pads	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Interior - Resecure Plywood as Needed	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Stack Adjusters / S-cams / Brake adjustment - Lubricate & adjust	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DOT Inspected - Sticker Applied	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Suspension / U-Bolts / Springs	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	California BIT Inspected & Passed	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired
<input checked="" type="checkbox"/>	Flatbed Winches - Lubricate and Cycle	Repaired	<input type="checkbox"/>	<input checked="" type="checkbox"/>	NOTES:	Repaired	<input type="checkbox"/>	<input type="checkbox"/>	Repaired

TIRES (in 32nds)

Axle	Position	PSI	Brand	TD	Position		PSI
					RO Front	RI Front	
1	LO Front	100	GY	6	RO Front	100	100
	LI Front	100	650	9	RI Front	100	100
	LO Middle				RO Middle		
2	LI Middle				RI Middle		
	LO Rear	100	GY	11	RO Rear	100	100
3	LI Rear	100	GY	10	RI Rear	100	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth			
			L Front	R Front	L Middle
1	L Front	18/32			
	R Front	16/32			
2	L Middle				
	R Middle				
3	L Rear	16/32			
	R Rear	16/32			

Hubo: 0
 Engine Hrs: _____
 Prot. Time: _____
 Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: [Signature] (Inspector signature)
 Inspection Date: 3-28-24

Print Name: Sustin Hobbs

Company Name: B&B TRUCK AND TRAILER SERVICES LLC