

FHWA Annual Vehicle Inspection Report

TAYLOR'S
EQUIPMENT REPAIR & WELDING

509 Whitehead Road
Fayetteville, NC 28312
(910) 323-5558

Date: 12/1/2023
Fleet #: TRAILER

Motor Carrier Operator: OID WADE	Inspector's Name: ROBERT TAYLOR
Address: 921 WHITCOMB DRIVE	This inspector meets the qualification requirements in section 396.19 <input checked="" type="checkbox"/> Yes
City, State, Zip: FAYETTEVILLE, NC 28311	VIN #: 1UYFS2537CA467113
<input type="checkbox"/> Tractor <input checked="" type="checkbox"/> Trailer <input type="checkbox"/> Truck <input type="checkbox"/> Other	Make: UTILITY
	Year: 2011 Model: TRAILER

OK	Needs Repair	Repair Date		OK	Needs Repair	Repair Date		OK	Needs Repair	Repair Date					
✓			1. Brake System a. Service Brakes b. Parking Brake System c. Brake Drums or Rotors d. Brake Hoses e. Brake Tubing f. Low pressure warning device g. Tractor Protection Valve h. Air Compressor i. Electric Brakes j. Hydraulic Brakes k. Vacuum System		N/A		4. Fuel System a. Visible leaks b. Fuel Tank Filler Cap Missing c. Fuel Tank Security Attached	✓			9. Frame a. Frame Members b. Tire & Wheel Clearance c. Adjustable Axle Assemblies (Siding Subframes)				
✓					N/A				✓				10. Tires a. Tires on any steering axle b. All other tires		
✓					N/A				✓					11. Wheels and rims: a. Lock or side ring b. Wheels & Rims c. Fasteners d. Welds	
✓					N/A				✓						12. Windshield Glazing Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter. (reference 393.60 for exceptions)
✓					N/A				✓						
	N/A		2. Coupling Devices a. Fifth Wheels b. Pinde Hooks c. Drawbar/Towbar Eye d. Drawbar/Towbar Tongue e. Safety Devices f. Saddle Mounts		N/A		5. Lighting Devices All lighting devices and reflectors required by Section 393 shall be operable.	✓							
	N/A				✓										
	N/A					N/A									
	N/A					N/A									
	N/A					N/A									
	N/A		3. Exhaust System a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment. b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3). c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply or any combination part of the motor vehicle.		N/A		6. Safe Loading a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway. b. Protection against shifting cargo	✓							
	N/A					N/A									
	N/A					N/A									
	N/A					N/A									
	N/A					N/A									
	N/A				N/A		7. Steering Mechanism a. Steering Wheel Free Play b. Steering Column c. Front axle beam and all steering components other than steering column d. Steering/Gear Box e. Pitman Arm f. Power Steering g. Ball and Socket joints h. Tie Rods & Drag Links i. Nuts j. Steering System	✓							
	N/A				N/A										
	N/A				N/A										
	N/A				N/A										
	N/A				N/A										
	N/A				N/A		8. Suspension: a. Any u-bolts, spring hangers or other axle positioning parts cracked, broken, loose or missing resulting in shifting of an axle from its normal position. b. Spring Assembly c. Torque, Radius or Tracking Components	✓							
	N/A				N/A										
	N/A				N/A										
	N/A				N/A										
	N/A				N/A										

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: X OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396.