



HYUNDAI
Translead

FMCSA ANNUAL INSPECTION FORM

HYUNDAI TRANSLEAD

Plant: Blvd. Hyundai No. 41, Col. Ampliación Constitución,
Playas de Rosarito, Baja California, MX. CP 22707
Corporate Office: 8880 Rio San Diego Drive, Ste # 600
San Diego, CA 92108

Inspection Facility: HT Rosarito Plant	Unit Number: 11111111	Hubodometer (if applicable): OK
City and State: Rosarito, Baja California, MX.	Customer: 11111111	S.A.P. Number: 30021933
Inspector Name: Fernando Giles	VIN Number: 11111111	License Plate Number: 479432T
Inspection Date: 07/20/2012 <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Repair Date:	Year / Model: 2011/NC2530152-A18

OK	NEEDS REPAIR	ITEMS INSPECTED	OK	NEEDS REPAIR	ITEMS INSPECTED
		BRAKE SYSTEM			SAFE LOADING
/		Service Brakes			Part(s) of vehicle or condition of loading such as spare tire or any part of the load or dunnage can fall onto the roadway
/		Parking Brake System	N		
/		Brake Drums or Rotors		A	
/		Brake Hose			
/		Brake Tubing			Protection against shifting cargo
/		Audible Air Leaks			STEERING MECHANISM
					For units with Steerable Rear Axle.
		COUPLING DEVICES			SUSPENSION
/		Fifth Wheels / Upper Coupler			Any U Bolt(s), spring hanger(s) or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from it's normal position
		Pintle Hooks			
		Drawbar / Towbar Eye			
N/A		Drawbar / Towbar Tongue	/		
		Safety Devices	/		
		Saddle-Mounts	/		Spring assembly
					Torque, radius or tracking component
		EXHAUST SYSTEM / REFRIGERATED UNITS			FRAME
N/A		No part of the exhaust system of any motor vehicle shall be located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle	/		Frame members
			/		Tire and Wheel Clearance
			/		Adjustable Axle Assemblies (Sliding Sub-Frames).
			/		TIRES
		FUEL SYSTEM / REFRIGERATED UNITS			WHEELS AND RIMS
		Visible leak	N/A		Lock or Side Ring
N/A		Fuel tank filler cap missing	/		Wheels and Rims
		Fuel tank securely attached	/		Fasteners
			/		Welds
		LIGHTING DEVICES			UNIT NUMBERS DISPLAYED
/		All lighting devices and reflectors required by Section 393 shall be operable.			SPLASH GUARDS
			/		Driver Side
			/		Passenger Side

I have inspected the vehicle described above and certify that all entries are true and correct. I certify that this inspection meets the requirements of 49 CFR Part 396.17 and is in accordance with Appendix G to Subchapter B, Minimum Periodic Inspection Standards, and the vehicle has passed / failed as indicated above.

INSPECTOR'S NAME (Please Print): Fernando Giles

INSPECTOR'S SIGNATURE: _____