



FHWA - PM

Branch Information

KCO69

Trailer Number: PS193162

License Number: AN5481 OK

HUB Reading: 131624

Registered Owner: Premier Trailer Leasing, Inc.

Serial Number: KK140203

Location Inspection Performed: KCO69

Items Inspected and Checked	OK	Defective	Repairs Performed	
Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Reflectors	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Wiring	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Brakes - Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Brakes - Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Brakes - All Adjusted	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Brake Shoe Measurements	Right Front	<u>5</u> /8ths	Left Front	<u>5</u> /8ths
	Right Rear	<u>8</u> /8ths	Left Rear	<u>7</u> /8ths
Airlines	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Kingpin	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Rear Impact Guard	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Wheels & Rims	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Frame Assembly	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Axles	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Wheel Seals	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Check Oil Levels in Hubs	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Lubrication: Slack Adjusters	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Lubrication: Cam Bushings	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Lubrication: Landing Legs	<input checked="" type="checkbox"/>	<input type="checkbox"/>		

Tires - Air All to 100 PSI

	Tread Depth Readings		Current Air Pressure		Tread Depth Readings		Current Air Pressure
LFO	<u>8</u>	<u>/32nds</u>	<u>100</u>	RFO	<u>8</u>	<u>/32nds</u>	<u>100</u>
LFI	<u>8</u>	<u>/32nds</u>	<u>100</u>	RFI	<u>8</u>	<u>/32nds</u>	<u>100</u>
LRO	<u>11</u>	<u>/32nds</u>	<u>100</u>	RRO	<u>15</u>	<u>/32nds</u>	<u>100</u>
LRI	<u>12</u>	<u>/32nds</u>	<u>100</u>	RRI	<u>8</u>	<u>/32nds</u>	<u>100</u>

I certify that this trailer was inspected on this 17 day of July, 2024 and made all FHWA-PI 49 C.F.R. Part #396.17 through .23 requirements.

L&W Fleet Services
Name of Company Performing Inspection/Repairs

Isaac Lewis
Inspectors Name (Please Print & Sign)