




DATE : 10-07-2024
LOCATION : 742 - Holland, MI
INSPECTOR : Israel Jimenez

DOT INSPECTION — Passed

4005019171 - Trailer

MOTOR CARRIER OPERATOR : ICD FREIGHT INC	TRACTOR NUMBER :
ADDRESS : 13202 W 98th St	TRAILER NUMBER : 201587
CITY, STATE, ZIP CODE : Lenexa, KS 66215-1359	VIN NUMBER : 3H3V532C0LR227437
DRIVER NAME : Kel	LICENSE PLATE : AK2690 STATE : OK



1. BRAKE SYSTEM	
Pass	a. Service Brakes
Pass	b. Parking Brake System
Pass	c. Brake Drums or Rotors
Pass	d. Brake Hose
Pass	e. Brake Tubing
NA	i. Electric/Disc Brakes
NA	j. Hydraulic Brakes
Pass	l. Antilock Brake System
Pass	m. Automatic Brake Adjusters
3. EXHAUST SYSTEM	
NA	a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment
NA	b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3)
NA	c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor
4. FUEL SYSTEM	
NA	a. Visible leak
NA	b. Fuel tank filler cap missing
NA	c. Fuel tank securely attached
5. LIGHTING DEVICES	
Pass	All lighting devices and reflectors required by Section 393 shall be operable.
6. SAFE LOADING	
NA	a. Part(s) of the vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway
Pass	b. Protection against shifting cargo
Pass	c. Container securement devices on intermodal equipment

8. SUSPENSION	
Pass	a. Any U-bolt(s), spring hangers or other axle positioning part(s) cracked, broken, loose or missing, resulting in shifting of an axle from its normal position
Pass	b. Spring Assembly
Pass	c. Torque, Radius or Tracking Components
9. FRAME	
Pass	a. Frame Members
Pass	b. Tire and Wheel Clearance
Pass	c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES	
Pass	b. All other tires
11. WHEELS	
NA	a. Lock or Side Ring
Pass	b. Wheels and Rims
Pass	c. Fasteners
Pass	d. Welds
15. REAR IMPACT GUARD	
Pass	a. In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER/GENERAL NOTES	
List any other condition(s) which may prevent safe operation of this vehicle	
Lf brake cracked	
Trailer Lube: No	

TIRE AND BRAKE MEASUREMENTS							
10 9		1		BRAKE STROKE		10 10	
32NDS	32NDS	IN		1 1/8	IN	32NDS	32NDS
85	95	3/4		3/4	IN	80	85
PSI	PSI	IN				PSI	PSI
				BRAKE SHOE			
8 8		1		BRAKE STROKE		11 11	
32NDS	32NDS	IN		1	IN	32NDS	32NDS
85	85	5/8		5/8	IN	100	110
PSI	PSI	IN				PSI	PSI
				BRAKE SHOE			

This inspection was completed according to terms for qualifications in accordance with 49CFR-396

Electronic Signature: Israel Jimenez