



# FHWA - PM

Branch Information

KCO69

Trailer Number: PS192879

License Number: \_\_\_\_\_

HUB Reading: 315515

Registered Owner: Premier Trailer Leasing, Inc.

Serial Number: \_\_\_\_\_

Location Inspection Performed: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Items Inspected and Checked	OK		Defective		Repairs Performed
	Right Front	Right Rear	Left Front	Left Rear	
Lights	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Reflectors	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wiring	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - Front	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - Rear	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - All Adjusted	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brake Shoe Measurements					
			4 /8ths	4 /8ths	
			4 /8ths	4 /8ths	
Airlines	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Kingpin	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Rear Impact Guard	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wheels & Rims	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Frame Assembly	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Suspension	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Axles	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wheel Seals	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Check Oil Levels in Hubs	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Slack Adjusters	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Cam Bushings	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Landing Legs	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

**Tires - Air All to 100 PSI**

Tread Depth Readings		Current Air Pressure	Tread Depth Readings		Current Air Pressure
LFO	12 /32nds	100	RFO	12 /32nds	100
LFI	12 /32nds	100	RFI	12 /32nds	100
LRO	12 /32nds	100	RRO	12 /32nds	100
LRI	12 /32nds	100	RRI	12 /32nds	100

I certify that this trailer was inspected on this 17 day of October, 2024 and made all FHWA-PI 49 C.F.R. Part #396.17 through .23 requirements.

Joe Williams Stone  
Name of Company Performing Inspection/Repairs

JOE WILLIAMS Stone  
Inspectors Name (Please Print & Sign)