

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
1230244	53159
DATE 12-30-24	

MOTOR CARRIER OPERATOR <i>ICD Freight</i>	INSPECTOR'S NAME (PRINT OR TYPE) <i>Tyler Smith</i>
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <i>Lenexa, KS</i>	VEHICLE IDENTIFICATION ( <input checked="" type="checkbox"/> AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <i>PL 410 416</i>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>6. SAFE LOADING</b>				<b>12. WINDSHIELD GLAZING</b>
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure	✓			<b>13. WINDSHIELD WIPERS</b>
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose	✓			<b>7. STEERING MECHANISM</b>			<b>14. MOTORCOACH SEATS</b>	
✓			e. Brake Tubing	✓			a. Steering Wheel Free Play	✓			Seats securely fastened to the vehicle structure.
			f. Low Pressure Warning Device	✓			b. Steering Column	✓			<b>15. REAR IMPACT GUARD</b>
			g. Tractor Protection Valve	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
			h. Air Compressor	✓			d. Steering Gear Box	✓			<b>16. OTHER</b>
			i. Electric Brakes	✓			e. Pitman Arm	✓			List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes	✓			f. Power Steering	✓			
			k. Vacuum Systems	✓			g. Ball and Socket Joints	✓			
			l. Antilock Brake System	✓			h. Tie Rods and Drag Links	✓			
			m. Automatic Brake Adjusters	✓			i. Nuts	✓			
			<b>2. COUPLING DEVICES</b>				<b>8. SUSPENSION</b>				
			a. Fifth Wheels	✓			a. Axle Positioning Parts	✓			
			b. Pintle Hooks	✓			b. Spring Assembly	✓			
			c. Drawbar/Towbar Eye	✓			c. Torque, Radius or Tracking Components	✓			
			d. Drawbar/Towbar Tongue	✓			<b>9. FRAME</b>				
			e. Safety Devices	✓			a. Frame Members	✓			
			f. Saddle-Mounts	✓			b. Tire and Wheel Clearance	✓			
			<b>3. EXHAUST SYSTEM</b>				<b>10. TIRES</b>				
			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			a. Steer-Axle Tires	✓			
			b. Bus: No leaking/ discharging in violation of standard.	✓			b. All Other Tires	✓			
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			c. Speed-Restricted Tires	✓			
			<b>4. FUEL SYSTEM</b>				<b>11. WHEELS AND RIMS</b>				
			a. No visible leak.	✓			a. Lock or Side Ring	✓			
			b. Fuel Tank Filler Cap	✓			b. Wheels and Rims	✓			
			c. Fuel tank securely attached.	✓			c. Fasteners	✓			
			<b>5. LIGHTING DEVICES</b>				<b>11. WHEELS AND RIMS</b>				
			All required lights/reflectors operable.	✓			d. Welds	✓			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION:  OK,  X NEEDS REPAIR,  NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

**CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.**