Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT W85649	1JJV532D8LL189547	2020	WABASH	ME 436949Z

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

☑	Glad Hands & Rubber Grommets	Repaired	☑	Sub-Frame – Slide Rails and Crossmembers	Repaired
☑	7-Way Electrical Plug	Repaired	☑	Aerodynamic Side Skirts	Repaired
☑	Registration, Valid License Plate and sticker	Repaired	☑	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	Repaired
☑	Lights, Wiring and Splice Conditions	Repaired	☑	Proper Lubricant Level in each Wheel End - Fill if necessary	Repaired
☑	Exterior Trailer - Body Condition and Coupling Device	Repaired	☑	Wheels - Check for Cracks / Tire Matching	Repaired
☑	Corner Locking Devices	Repaired	☑	Tires - free of impermissible damage or wear	Repaired
☑	Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle	Repaired	☑	Lugnuts – Torque to 450-500 ft/lbs – Set wrench to 500 ft/lbs	Repaired
M	Fuel Tank and Fuel System (Reefer)	Repaired	☑	Metal Flow-Thru Valve Stem Caps	Repaired
☑	Air Brake System - Test for Leaks	Repaired	☑	Conspicuity Tape–Side Panels, Rear Doors, Headboards	Repaired
M	Dump Valve (Air Ride Only) - Testoperation and check for Leaks	Repaired	☑	Mudflaps, Brackets, and Rubber Dock Bumpers	Repaired
☑	ABS System - Actuate	Repaired	☑	Rear Impact Guard	Repaired
☑	Air Lines - Check for damage / wear / chaffing	Repaired	☑	Doors – Proper Operation	Repaired
☑	Suspension Hangers	Repaired	☑	Door Hold Backs and Pull Handles - Present & Functional	Repaired
☑	Air Tank and Mounting Brackets	Repaired	☑	All Hinges, Rollers, Locks – Lubricate	Repaired
M	Brakes - Drums / Linings /Air Chambers	Repaired	☑	Interior Trailer – Floor, Roof, and Side Walls	Repaired
☑	Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads	Repaired	☑	Interior – Resecure Plywood as Needed	Repaired
☑	Slack Adjusters / S-cams / Brake adjustment – Lubricate & adjust	Repaired	☑	DOT Inspected – Sticker Applied	Repaired
☑	Suspension / U-Bolts / Springs	Repaired	M	California BIT Inspected & Passed	Repaired
M	Flatbed Winches – Lubricate and Cycle	Repaired		NOTES:	

TIRES (In 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	7	BS	100	RO Front	8	BS	100
	LI Front	9		100	RI Front	8		100
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	8	BS	100	RO Rear	7	BS	100
	LI Rear	8		100	RI Rear	8		100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	20mm
	R Front	
2	L Middle	
	R Middle	
3	L Rear	20mm
	R Rear	21 mm

Hubo: 59393

Engine Hrs:

Prot. Time:

Fuel 8ths:

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: _____ (inspector signature)

Inspection Date: 6-17-24

Print Name: Justin Hostetter

Company Name: B&B TRUCK AND TRAILER SERVICES LLC