ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
225251	53158
DATE 2/25/25	

MOTOR CARRIER OPERATOR: ICD Freight	INSPECTOR'S NAME (PRINT OR TYPE): Tirath Singh
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES
CITY, STATE, ZIP CODE: Lenexa, KS	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: NH409282
VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
			f. Low Pressure Warning Device
NA			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
			l. Antilock Brake System
			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
			a. Fifth Wheels
			b. Pintle Hooks
NA			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
			e. Safety Devices
			f. Saddle-Mounts
3. EXHAUST SYSTEM			
			a. No leaks forward of/ directly below the driver/ sleeper compartment.
NA			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
NA			a. No visible leak.
			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
6. SAFE LOADING			
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
NA			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
N			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links NH409282
			i. Nuts
			j. Steering System
8. SUSPENSION			
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
9. FRAME			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
NA			a. Steer-Axle Tires
✓			b. All Other Tires
✓			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
NA			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
225251			**12. WINDSHIELD GLAZING**
NA			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
NA			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
NA			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle. X

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

DUPLICATE