



FHWA - PM

Branch Information

KC069

Trailer Number: 85210107
License Number: 0869077 TN
HUB Reading: 193862

Registered Owner: Premier Trailer Leasing, Inc.
Serial Number: MD 308931

Location Inspection Performed: KC069

Items Inspected and Checked	OK		Defective		Repairs Performed
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Reflectors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wiring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brakes - All Adjusted	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Brake Shoe Measurements	Right Front	<input checked="" type="checkbox"/>	5 /8ths	Left Front	5 /8ths
	Right Rear	<input checked="" type="checkbox"/>	4 /8ths	Left Rear	4 /8ths
Airlines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Kingpin	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Rear Impact Guard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wheels & Rims	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Frame Assembly	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Axles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Wheel Seals	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Check Oil Levels in Hubs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Slack Adjusters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Cam Bushings	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Lubrication: Landing Legs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Tires - Air All to 100 PSI

	Tread Depth Readings		Current Air Pressure		Tread Depth Readings		Current Air Pressure
LFO	9	/32nds	100	RFO	11	/32nds	100
LFI	10	/32nds	100	RFI	7	/32nds	100
LRO	10	/32nds	100	RRO	7	/32nds	100
LRI	10	/32nds	100	RRI	6	/32nds	100

I certify that this trailer was inspected on this 17 day of July, 2024 and made all FHWA-PI 49 C.F.R. Part #396.17 through .23 requirements.

L&W Fleet Services
Name of Company Performing Inspection/Repairs

Isaac Lewis
Inspectors Name (Please Print & Sign)