



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHDR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

Result	<input checked="" type="checkbox"/> OK	Status	RC - Repair completed	CD - Customer decision not to repair
	<input checked="" type="checkbox"/> Follow-up Needed		ND - No defect found after further review	JD - Job deferred to a later time
	<input type="checkbox"/> Inspected/Adjusted		CR - Customer Repaired/Replaced; Penske Verified	
	<input type="checkbox"/> N/A Not Applicable	Note: Shaded steps indicates DOT required safety checks.		

UNIT IN-CAB INSPECTION

Inspect all items listed for condition / mounting / operation and wear.

	Result	Reading	Inspector (Changed by)
All items listed were inspected for condition, mounting, operation, leaks and free of debris as required	<input type="checkbox"/>		Jean-Luc Ferguson
Technicians followed all Penske safety guidelines and procedures while performing the PM	<input type="checkbox"/>		Jean-Luc Ferguson
Any item that failed the initial technician's inspection had a job added and was reviewed by a supervisor for follow up work as needed	<input type="checkbox"/>		Jean-Luc Ferguson
All equipment and tools used were Penske approved	<input type="checkbox"/>		Jean-Luc Ferguson
Driver side step and grab handles	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
All dashboard lamps and audible warning devices	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
All gauges, starter motor and ignition switch	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
All interior and dash lights and all switches	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
OEM manuals and instructions installed in proper locations	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up CONCERN OR ISSUE WITH THE OEM MANUAL REGEN INSTRUCTIONS</p> <p>Status ND - No defect found after further review</p> <p>Changed by Vesper Williams</p> </div>			
Heater, defroster, AC, and AC controls	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up CONCERN WITH THE AC, DEFROSTER OR HEATER OPERATION.</p> <p>Status RC - REPLACE AIR CONDITIONING - A/C CONDENSER CORE</p> <p>Done By [HAPPYDAN] 12/30/2024 RO# 0387-414927</p> </div>			
Truck is not making any unusual noise while AC is running	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
All glass for damage or rock chips	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
Windshield wipers and washer system	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up WIPER BLADE IS NOT FUNCTIONING PROPERLY</p> <p>Status RC - REPLACE WINDSHIELD WIPER BLADE</p> <p>Done By [JEAN] 01/15/2025 RO# 0387-414927</p> </div>			
No dash warning lights or collision mitigation lights were active	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
Windshield was free of debris so the collision mitigation device can work properly	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
Collision mitigation device	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
All horns: electric and/or air	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
Steering wheel tilt and telescoping feature	<input checked="" type="checkbox"/>		Jean-Luc Ferguson
Steering wheel excessive play	<input checked="" type="checkbox"/>		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHDR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT IN-CAB INSPECTION

Inspect all items listed for condition / mounting / operation and wear.

Radio, speakers, DC power outlets, USB and any other accessories	✓		Jean-Luc Ferguson
Cruise control switch	✓		Jean-Luc Ferguson
Engine brake	✓		Jean-Luc Ferguson
Listened for any extra loud noises, that would limit the driver from hearing emergency sirens, while inside the cab with all doors and windows closed	✓		Jean-Luc Ferguson
All power windows and mirrors	✓		Jean-Luc Ferguson
Driver side door lock and latch	✓		Jean-Luc Ferguson
Passenger side door lock and latch	✓		Jean-Luc Ferguson
Passenger side seat mounting and seat belt	✓		Jean-Luc Ferguson
Passenger side seat cushions	✓		Jean-Luc Ferguson
Interior dash HVAC filter	✓		Jean-Luc Ferguson
Spare fuse kit present (if applicable)	✓		Jean-Luc Ferguson
Passenger side heated mirror <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up PASSENGER SIDE HEATED MIRROR ISSUE OR CONCERN Status ND - No defect found after further review Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
Sleeper restraints	✓		Jean-Luc Ferguson
Sleeper controls and mattress	✓		Jean-Luc Ferguson
Power inverter outlets have power	✓		Jean-Luc Ferguson
HVAC bunk filter	📄		Jean-Luc Ferguson
All safety related items <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up SAFETY ITEM CONCERN Status ND - No defect found after further review Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
Fire extinguisher: proper type and charge state <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up FIRE EXTINGUISHER NEEDS REPLACED Status RC - REPLACE FIRE EXTINGUISHER Done By [JEAN] 01/15/2025 RO# 0387-414927</p> </div>	⊗		Jean-Luc Ferguson
Driver side seat mounting and seat belt	✓		Jean-Luc Ferguson
Driver side seat cushions	✓		Jean-Luc Ferguson
Driver side heated mirror <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up DRIVER SIDE HEATED MIRROR ISSUE OR CONCERN Status ND - No defect found after further review Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
Back up alarm	✓		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT IN-CAB INSPECTION

Inspect all items listed for condition / mounting / operation and wear.

Clutch pedal (if equipped), treadle (foot) valve (if applicable) and the accelerator pedal	✓		Jean-Luc Ferguson
All transmission shifting controls	✓		Jean-Luc Ferguson
Any damaged items within the cab area	✓		Jean-Luc Ferguson
5th wheel slider locks	✓		Jean-Luc Ferguson

UNIT WALK AROUND INSPECTION

Inspect all items listed for condition / mounting / operation and wear. Check all fluids are within normal operating range, no signs of leaks. Perform and record all test results as applicable.

	Result	Reading	Inspector (Changed by)
All battery box items	✓		Jean-Luc Ferguson
All battery wiring connections and wire ends	✓		Jean-Luc Ferguson
Battery top area free of dirt and debris	✓		Jean-Luc Ferguson
Connected battery charger to the unit	📄		Jean-Luc Ferguson
Driver side fender mirror and bracket	✓		Jean-Luc Ferguson
Front bumper, license plate holder, grille, grille guard assembly, headlight lenses and fog light lenses	✓		Jean-Luc Ferguson
Front facing radar detection device in the bumper	✓		Jean-Luc Ferguson
Passenger side fender mirror and bracket	✓		Jean-Luc Ferguson
All hood latches	✓		Jean-Luc Ferguson
HVAC housing, air intake and AC system	✓		Jean-Luc Ferguson
Inspected air filter LED minder light for proper operation.	✓		Jean-Luc Ferguson
Cab HVAC filter	📄		Jean-Luc Ferguson
All door hinges, latches and locks	📄		Jean-Luc Ferguson
Passenger side mirrors and brackets	✓		Jean-Luc Ferguson
Passenger side step and grab handles	✓		Jean-Luc Ferguson
Passenger side fuel tank, lines, brackets and side fairings (if applicable)	✓		Jean-Luc Ferguson
Deck plate	✓		Jean-Luc Ferguson
Passenger side cab suspension air bags, cab shocks, and cab torque arm	✓		Jean-Luc Ferguson
Passenger side auxiliary equipment	✓		Jean-Luc Ferguson
Rear license plate holder, mud flaps and brackets	✓		Jean-Luc Ferguson
All safety chains, pintle hook, rear or ICC bumper, reflectors and reflective tape	✓		Jean-Luc Ferguson
Driver side auxiliary equipment	✓		Jean-Luc Ferguson
Driver side cab suspension air bags, cab shocks, and cab torque arm	✓		Jean-Luc Ferguson
Trailer light cord socket: lubed as needed	✓		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT WALK AROUND INSPECTION

Inspect all items listed for condition / mounting / operation and wear. Check all fluids are within normal operating range, no signs of leaks. Perform and record all test results as applicable.

Trailer light plug and cord	✓		Jean-Luc Ferguson
Light cord, power cord, trailer air hoses not loose, dragging on catwalk, or chaffing	✓		Jean-Luc Ferguson
Three in one light cord counter clockwise loop length and all clamps in the right position	✓		Jean-Luc Ferguson
Glad hand and glad hand holders	✓		Jean-Luc Ferguson
Replaced glad hand seals	📄		Jean-Luc Ferguson
Driver side fuel tank, fuel tank cap, lines, brackets and fairings	✓		Jean-Luc Ferguson
DEF tank, filler cap, label, and header	✓		Jean-Luc Ferguson
Driver side mirrors and brackets	✓		Jean-Luc Ferguson
Inspected entire unit for any physical damage	✓		Jean-Luc Ferguson
All exterior lights	✓		Jean-Luc Ferguson
All standard Penske decals and QR codes present and in good condition	✓		Jean-Luc Ferguson
Lockout / Tagout Procedure followed	📄		Jean-Luc Ferguson
Replaced any HVAC filters if needed	📄		Jean-Luc Ferguson

UNIT UPPER INSPECTION

Inspect all items listed for condition / mounting / operation and wear. Check all fluids are within normal operating range, no signs of leaks. Perform and record all test results as applicable.

	Result	Reading	Inspector (Changed by)
Oil level prior to draining oil	📄		Jean-Luc Ferguson
Drained fuel/water separator(s) and refilled	📄		Jean-Luc Ferguson
Fuel water separator	✓		Jean-Luc Ferguson
Coolant freeze point temperature	✓		Jean-Luc Ferguson
Coolant condition and level	⊗		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up UNIT COOLANT LEVEL CONCERN Status RC - REPLACE TANK-SURGE Done By [HAPPYDAN],[JEAN] 12/30/2024 RO# 0387-414927</p> </div>			
Driver side steer axle suspension items including, spring, shock, strut, center bolt and U-bolts	✓		Jean-Luc Ferguson
Steering column assembly, U-joints and steering gear box	✓		Jean-Luc Ferguson
Power steering and clutch master cylinder	✓		Jean-Luc Ferguson
Power steering reservoir and clutch master cylinder fluid	✓		Jean-Luc Ferguson
DETROIT ENGINES ONLY: Fuel injector lines and seals for leaks	✓		Jean-Luc Ferguson
All upper electrical harness, lines, fittings, mountings and bolts	✓		Jean-Luc Ferguson
Fan shroud, radiator, condenser and charge air cooler	✓		Jean-Luc Ferguson
All belts, pulleys, idlers and tensioners	✓		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT UPPER INSPECTION

Inspect all items listed for condition / mounting / operation and wear. Check all fluids are within normal operating range, no signs of leaks. Perform and record all test results as applicable.

Fan hub bearings and brackets	✓		Jean-Luc Ferguson
Alternator and wiring	✓		Jean-Luc Ferguson
From the top side: all engine bolts, bushings and mounts	✓		Jean-Luc Ferguson
Crankcase breather	✓		Jean-Luc Ferguson
Passenger side steer axle spring, shock, strut, center bolt and U-bolts	✓		Jean-Luc Ferguson
Windshield washer reservoir topped off	✓		Jean-Luc Ferguson
Doser valve and doser injection valve	✓		Jean-Luc Ferguson
Entire exhaust system: clamps, brackets, wiring, lines, hoses, sensors, etc	✓		Jean-Luc Ferguson

UNIT TIRE INSPECTION

Inspect all items for condition / mounting / operation and wear. Use only Penske approved air inflation device. Follow all safety guidelines when working with tires.

	Result	Reading	Inspector (Changed by)
For each wheel position the wheel was inspected for mounting lug nut(s) securement, condition of the tire, condition of the wheel/rim and flange gasket leaks	📄		Jean-Luc Ferguson
Marked the top of each tire with the current air pressure and tread depth readings	📄		Jean-Luc Ferguson
Connected the air fill hose and ensured all driver side tires filled properly	📄		Jean-Luc Ferguson
Driver side wheel bearing proper oil condition, level and flange gasket	✓		Jean-Luc Ferguson
Driver side bearing vent cap hole is open	📄		Jean-Luc Ferguson
Driver side steer axle tread depth reading	✓	15 32nds	Jean-Luc Ferguson
Driver side steer tire irregular wear, misalignment, damage, under inflation or wrong tire	✓		Jean-Luc Ferguson
Driver side steer position defects related to the studs, lug nuts, flange gasket, rim or wheel assembly	✓		Jean-Luc Ferguson
Driver side steer axle clunk test	✓		Jean-Luc Ferguson
Driver side 1st rear axle inner tread depth reading	✓	13 32nds	Jean-Luc Ferguson
Driver side 1st rear axle outer tread depth reading	✓	15 32nds	Jean-Luc Ferguson
Driver side 2nd rear axle inner tread depth reading	✓	10 32nds	Jean-Luc Ferguson
Driver side 2nd rear axle outer tread depth reading	✓	10 32nds	Jean-Luc Ferguson
Driver side rear tire issues	✓		Jean-Luc Ferguson
Driver side rear position defects related to the studs, lug nuts, flange gasket, rim or wheel assembly	✓		Jean-Luc Ferguson
Passenger side 2nd rear axle inner tread depth reading	✓	9 32nds	Jean-Luc Ferguson
Passenger side 2nd rear axle outer tread depth reading	✓	25 32nds	Jean-Luc Ferguson
Passenger side 1st rear axle inner tread depth reading	✓	13 32nds	Jean-Luc Ferguson
Passenger side 1st rear axle outer tread depth reading	✓	25 32nds	Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHDR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT TIRE INSPECTION

Inspect all items for condition / mounting / operation and wear. Use only Penske approved air inflation device. Follow all safety guidelines when working with tires.

Passenger side rear tire issues <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> <p>Follow-Up PASSENGER'S SIDE REAR TIRE(S) ISSUE OR CONCERN. ROTATION ISSUE Status RC - DUAL MATING CORRECTION - DUAL TIRE Done By [LRM] 01/16/2025 RO# 0387-414927</p> </div>	⊗		Jean-Luc Ferguson
Passenger side rear position defects related to the studs, lug nuts, flange gasket, rim or wheel assembly	✓		Jean-Luc Ferguson
Connected the air fill hose and ensured all passenger side tires filled properly	📄		Jean-Luc Ferguson
Passenger side wheel bearing proper oil condition, level and flange gasket	✓		Jean-Luc Ferguson
Passenger side bearing vent cap hole is open	📄		Jean-Luc Ferguson
Passenger side steer tread depth reading	✓	15 32nds	Jean-Luc Ferguson
Passenger side steer tire irregular wear, misalignment, damage, under inflation or wrong tire	✓		Jean-Luc Ferguson
Passenger side steer position defects related to the studs, lug nuts, flange gasket, rim or wheel assembly	✓		Jean-Luc Ferguson
Passenger side steer axle clunk test	✓		Jean-Luc Ferguson

UNIT LOWER INSPECTION

Inspect all items for condition / mounting / operation and wear. Check for any signs of leaks related to air / coolant / engine oil / fuel / rear axle or transmission.

	Result	Reading	Inspector (Changed by)
Inspected for leaks (air, oil, coolant, fuel, etc.) while completing PM	📄		Jean-Luc Ferguson
Drag link, tie rod, tie rod ends, pitman arm, front axle beam and all steering components	✓		Jean-Luc Ferguson
Air disc brake pads	📄		Jean-Luc Ferguson
Driver side steer axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Passenger side steer axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Steer axles brake lines, drums, rotors, lining, pads, chambers and calipers	✓		Jean-Luc Ferguson
From the bottom side: all engine bolts, bushings and mounts	✓		Jean-Luc Ferguson
Starter and wiring	✓		Jean-Luc Ferguson
Cab floor	✓		Jean-Luc Ferguson
All cab mounts, bolts and brackets	✓		Jean-Luc Ferguson
Entire exhaust system: clamps, brackets, wiring, lines, hoses, sensors, etc.	✓		Jean-Luc Ferguson
Diesel particulate filter (DPF) and diesel oxidation catalyst (DOC)	✓		Jean-Luc Ferguson
Exhaust leaks at the DPF / DOC, all sensors, control devices, tubes, nozzles, fittings, wiring harnesses, etc	✓		Jean-Luc Ferguson
Selective catalytic reduction (SCR) catalyst and all sensors, control devices, wiring, tubes, nozzles, fittings, etc	✓		Jean-Luc Ferguson
DEF lines, fittings, and electrical connections free of leaks, chaffing and routed properly	✓		Jean-Luc Ferguson
All air tanks, check valves, quick release valves, mountings and relay valves	✓		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT LOWER INSPECTION

Inspect all items for condition / mounting / operation and wear. Check for any signs of leaks related to air / coolant / engine oil / fuel / rear axle or transmission.

Drained water from the wet tank	✓		Jean-Luc Ferguson
Clutch, clutch linkage, and slave cylinder	N/A		Jean-Luc Ferguson
Bell housing bolts	✓		Jean-Luc Ferguson
Transmission oil level, topped off fluid as needed	✓		Jean-Luc Ferguson
Transmission main shaft rear bearing	✓		Jean-Luc Ferguson
Drive shafts, U-joints, slip joints and yoke nuts	✓		Jean-Luc Ferguson
Passenger side 1st drive axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Passenger side 2nd drive axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Driver side 2nd drive axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Driver side 1st drive axle brake pad or lining above minimum requirements	✓		Jean-Luc Ferguson
Issues found during rear axle clunk test	✓		Jean-Luc Ferguson
All brake components	✓		Jean-Luc Ferguson
All wheel seals	✓		Jean-Luc Ferguson
All rear axle springs, shocks, air bags, U-bolts, center bolts, equalizers, torque arms, brackets, leveling valve and linkage	✓		Jean-Luc Ferguson
All rear axle center bolts, equalizers, torque arms, leveling valve and linkage	✓		Jean-Luc Ferguson
All differential housing bolts, gaskets, pinion seals and bearings	✓		Jean-Luc Ferguson
Differential oil level and breather vents	⊗		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up DELETE</p> <p>Status ND - No defect found after further review</p> <p>Changed by Vesper Williams</p> </div>			
All cross members and frame rails	✓		Jean-Luc Ferguson
List of leaks (air, oil, coolant, fuel, etc) found while performing PM	⊗		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up DIFFERENTIAL IS LEAKING</p> <p>Status RC - REPLACE DIFFERENTIAL GASKET</p> <p>Done By [JEAN],LRM 01/16/2025 RO# 0387-414927</p> </div>			
Greased all fittings accessible from under the unit	📄		Jean-Luc Ferguson
Ensured that all components took grease properly while greasing lower side of unit	✓		Jean-Luc Ferguson
5th wheel mounting	✓		Jean-Luc Ferguson
5th wheel jaws and plate	⊗		Jean-Luc Ferguson
<div style="border: 1px solid black; padding: 5px;"> <p>Follow-Up FACTORY FIFTH WHEEL SETTING ADJUSTED OR SET INCORRECTLY</p> <p>Status RC - ADJUST 5TH WHEEL LOCKING JAWS</p> <p>Done By [JEAN] 12/28/2024 RO# 0387-414927</p> </div>			
Greased all fittings accessible from top side of unit	📄		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHDR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT LOWER INSPECTION

Inspect all items for condition / mounting / operation and wear. Check for any signs of leaks related to air / coolant / engine oil / fuel / rear axle or transmission.

Ensured all components took grease properly while greasing top side of unit	✓		Jean-Luc Ferguson
---	---	--	-------------------

UNIT FINAL INSPECTION

Inspect all required items.

	Result	Reading	Inspector (Changed by)
Emission label was present, readable, and displayed the build date	✓		Jean-Luc Ferguson
Download all ECM data to the repair order	✓		Jean-Luc Ferguson
Current road speed setting	📄	70	Jean-Luc Ferguson
Current cruise speed setting	📄	70	Jean-Luc Ferguson
Reviewed ECM download and recorded active fault codes <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up DURING E-TECHNICIAN DOWNLOAD, SYSTEM DISPLAYS ACTIVE OR INACTIVE FAULT CODES</p> <p>Status RC - REPAIR - SENSOR WIRING- TEMPERATURE, INTAKE MANIFOLD</p> <p>Done By [HAPPYDAN],[JEAN] 12/30/2024 RO# 0387-414927</p> </div>	⊗		Jean-Luc Ferguson
Reviewed ECM download and recorded any regeneration events <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up DELETE</p> <p>Status ND - No defect found after further review</p> <p>Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
When needed the vehicle health report was attached to the repair order	📄		Jean-Luc Ferguson
Removed battery charger and lubricated battery terminals	📄		Jean-Luc Ferguson
Shut engine off and verified oil filled to proper level	📄		Jean-Luc Ferguson
Performed Penske's electrical systems test	✓		Jean-Luc Ferguson
Starting system check <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up ISSUE OR CONCERN WITH THE ELECTRICAL SYSTEM TEST FOR THE STARTING SYSTEM</p> <p>Status ND - No defect found after further review</p> <p>Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
Charging system check <div style="border: 1px solid black; padding: 5px; margin: 5px 0;"> <p>Follow-Up UNIT HAS A CHARGING SYSTEM ISSUE OR CONCERN</p> <p>Status RC - SERVICE BATTERY / BATTERIES & CABLES</p> <p>Done By [HAPPYDAN],[LRM] 01/16/2025 RO# 0387-414927</p> </div>	⊗		Jean-Luc Ferguson
Electrical tester PM test number	📄	604	Jean-Luc Ferguson
Parking brake, tractor / trailer protection valve and trailer hand-brake control	✓		Jean-Luc Ferguson
Fan clutch, air governor, and low air warning for the primary and secondary air systems	✓		Jean-Luc Ferguson
One (1) minute brake test	✓		Jean-Luc Ferguson



Unit Number	Unit Type	Make	Current Odometer	Date
586333	TADC TRACTOR SLEEPER	2023 FREIGHTLINER T12664ST	268,804	12/28/2024
Customer Unit	VIN	Customer	RO Number	Inspection ID
	3AKJHHDR6PSNS5896	63061000-0387 ICD FREIGHT INC.	0387-414927	202412099878

UNIT FINAL INSPECTION

Inspect all required items.

Vehicle permits, registration, license, insurance card and state inspections were present and valid <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p>Follow-Up UNIT PAPERWORK CONCERN Status ND - No defect found after further review Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson
Certified Clean Idle sticker was present and readable	✓		Jean-Luc Ferguson
Installed updated Penske PM sticker on inside of unit	📄		Jean-Luc Ferguson
FHWA sticker placard was present and installed	✓		Jean-Luc Ferguson
New FHWA annual inspection certification sticker installed once all D.O.T. items passed <div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <p>Follow-Up INSTALL FHWA STICKER AFTER ALL DOT ITEMS HAVE BEEN REPAIRED Status ND - No defect found after further review Changed by Vesper Williams</p> </div>	⊗		Jean-Luc Ferguson

Electronic signature of persons certifying the inspection and all required repairs have been completed.

Inspection Approved by	SSO	Date
Levi Lane	600168688	01/17/2025

Additional Repairs Approved by	SSO	Date
Levi Lane	600168688	01/17/2025