

ANNUAL VEHICLE INSPECTION REPORT

| VEHICLE HISTORY RECORD | |
|------------------------|-------------------|
| REPORT NUMBER | FLEET UNIT NUMBER |
| 69262584 | H06006 |
| DATE 7-29-25 | |

| | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| MOTOR CARRIER OPERATOR ICD ADDRESS 13250 WEST 98th STREET CITY, STATE, ZIP CODE LENEXA KS 66215 VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER) | INSPECTOR'S NAME (PRINT OR TYPE) EDWARD HEILI THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER SVPVCS325 RM 414787 INSPECTION AGENCY/LOCATION (OPTIONAL) |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

VEHICLE COMPONENTS INSPECTED

| OK | NEEDS REPAIR | REPAIRED DATE | ITEM | OK | NEEDS REPAIR | REPAIRED DATE | ITEM |
|----|--------------|---------------|--------------------------------------------------------------------------------------------------------------|----|--------------|---------------|-------------------------------------------------------------------------------|
| | | | 1. BRAKE SYSTEM | | | | 6. SAFE LOADING |
| ✓ | | | a. Service Brakes | ✓ | | | a. Vehicle parts, load, dunnage, spare tire, etc., secured. |
| ✓ | | | b. Parking Brake System | ✓ | | | b. Front End Structure |
| ✓ | | | c. Brake Drums or Rotors | ✓ | | | c. Intermodal Container Securement Devices |
| ✓ | | | d. Brake Hose | NA | | | |
| ✓ | | | e. Brake Tubing | | | | |
| ✓ | | | f. Low Pressure Warning Device | | | | |
| ✓ | | | g. Tractor Protection Valve | | | | |
| ✓ | | | h. Air Compressor | | | | |
| ✓ | | | i. Electric Brakes | | | | |
| ✓ | | | j. Hydraulic Brakes | | | | |
| ✓ | | | k. Vacuum Systems | | | | |
| ✓ | | | l. Antilock Brake System | | | | |
| ✓ | | | m. Automatic Brake Adjusters | | | | |
| | | | 2. COUPLING DEVICES | | | | 7. STEERING MECHANISM |
| NA | | | a. Fifth Wheels | ✓ | | | a. Steering Wheel Free Play |
| NA | | | b. Pintle Hooks | ✓ | | | b. Steering Column |
| NA | | | c. Drawbar/Towbar Eye | ✓ | | | c. Front Axle Beam/All Other Steering Components |
| NA | | | d. Drawbar/Towbar Tongue | ✓ | | | d. Steering Gear Box |
| NA | | | e. Safety Devices | ✓ | | | e. Pitman Arm |
| NA | | | f. Saddle-Mounts | ✓ | | | f. Power Steering |
| | | | 3. EXHAUST SYSTEM | | | | 8. SUSPENSION |
| NA | | | a. No leaks forward of/directly below the driver/sleeper compartment. | ✓ | | | a. Axle Positioning Parts |
| NA | | | b. Bus: No leaking/discharging in violation of standard. | ✓ | | | b. Spring Assembly |
| NA | | | c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle. | ✓ | | | c. Torque, Radius or Tracking Components |
| | | | 4. FUEL SYSTEM | | | | 9. FRAME |
| NA | | | a. No visible leak. | ✓ | | | a. Frame Members |
| NA | | | b. Fuel Tank Filler Cap | ✓ | | | b. Tire and Wheel Clearance |
| NA | | | c. Fuel tank securely attached. | ✓ | | | c. Adjustable Axle Assemblies (Sliding Subframes) |
| | | | 5. LIGHTING DEVICES | | | | 10. TIRES |
| ✓ | | | All required lights/reflectors operable. | NA | | | a. Steer-Axle Tires |
| | | | | NA | | | b. All Other Tires |
| | | | | NA | | | c. Speed-Restricted Tires |
| | | | | NA | | | 11. WHEELS AND RIMS |
| | | | | NA | | | a. Lock or Side Ring |
| | | | | NA | | | b. Wheels and Rims |
| | | | | NA | | | c. Fasteners |
| | | | | NA | | | d. Welds |
| | | | | NA | | | 12. WINDSHIELD GLAZING |
| | | | | NA | | | No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions). |
| | | | | NA | | | 13. WINDSHIELD WIPERS |
| | | | | NA | | | No missing, damaged, or inoperable wipers. |
| | | | | NA | | | 14. MOTORCOACH SEATS |
| | | | | NA | | | Seats securely fastened to the vehicle structure. |
| | | | | NA | | | 15. REAR IMPACT GUARD |
| | | | | NA | | | In place, securely attached, proper size, proper placement (see 393.86). |
| | | | | NA | | | 16. OTHER |
| | | | | NA | | | List any other condition(s) which may prevent safe operation of this vehicle. |

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: OK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL