ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

RECORD NUMBER	FLEET UNIT NUMBER
69262528	PTLZ210072

DATE 07-25

MOTOR CARRIER OPERATOR: ICD	INSPECTOR'S NAME (PRINT OR TYPE): EDWARD M. HEES
ADDRESS: 13250 WEST 98th STREET	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19: ☒ YES
CITY, STATE, ZIP CODE: LENEXA KS 66215	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL): 3H3V532C5MR159072

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
NA	NA		f. Low Pressure Warning Device
			g. Tractor Protection Valve
			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
✓			a. Fifth Wheels
NA	NA		b. Pintle Hooks
			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
NA	NA		f. Saddle-Mounts
			3. EXHAUST SYSTEM
			a. No leaks forward of/ directly below the driver/ sleeper compartment.
NA	NA		b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
			a. No visible leak.
NA	NA		b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.
			6. SAFE LOADING
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
NA	NA		c. Intermodal Container Securement Devices
			7. STEERING MECHANISM
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
NA	NA		d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
NA	NA		a. Steer-Axle Tires
✓			b. All Other Tires
NA	NA		c. Speed-Restricted Tires
			11. WHEELS AND RIMS
NA	NA		a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
NA	NA		d. Welds
			12. WINDSHIELD GLAZING
NA	NA		No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
NA	NA		No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
NA	NA		Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION. ✓ OK. X NEEDS REPAIR. NA IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL