Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT W10920	1JJV532D9FL877254	2015	WABASH	ME 5379887

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK. X = Needs Further Attention R = Repaired N/A = Not Applicable

- [x] Glad Hands & Rubber Grommets — Repaired
- [x] 7-Way Electrical Plug — Repaired
- [x] Registration, Valid License Plate and sticker — Repaired
- [x] Lights, Wiring and Splice Conditions — Repaired
- [x] Exterior Trailer - Body Condition and Coupling Device — Repaired
- [N/A] Corner Locking Devices — Repaired
- [x] Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle — Repaired
- [N/A] Fuel Tank and Fuel System (Reefer) — Repaired
- [x] Air Brake System - Test for Leaks — Repaired
- [N/A] Dump Valve (Air Ride Only) - Testoperation and check for Leaks — Repaired
- [x] ABS System - Actuate — Repaired
- [x] Air Lines - Check for damage / wear / chaffing — Repaired
- [x] Suspension Hangers — Repaired
- [x] Air Tank and Mounting Brackets — Repaired
- [x] Brakes - Drums / Linings /Air Chambers — Repaired
- [N/A] Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads — Repaired
- [x] Slack Adjusters / S-cams / Brake adjustment – Lubricate & adjust — Repaired
- [x] Suspension / U-Bolts / Springs — Repaired
- [N/A] Flatbed Winches – Lubricate and Cycle — Repaired
- [x] Sub-Frame – Slide Rails and Crossmembers — Repaired
- [x] Aerodynamic Side Skirts — Repaired
- [x] Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage — Repaired
- [x] Proper Lubricant Level in each Wheel End - Fill if necessary — Repaired
- [x] Wheels - Check for Cracks / Tire Matching — Repaired
- [x] Tires - free of impermissible damage or wear — Repaired
- [x] Lugnuts – Torque to 450-500 ft/lbs – Set wrench to 500 ft/lbs — Repaired
- [x] Metal Flow-Thru Valve Stem Caps — Repaired
- [x] Conspicuity Tape–Side Panels, Rear Doors, Headboards — Repaired
- [x] Mudflaps, Brackets, and Rubber Dock Bumpers — Repaired
- [x] Rear Impact Guard — Repaired
- [x] Doors – Proper Operation — Repaired
- [x] Door Hold Backs and Pull Handles - Present & Functional — Repaired
- [x] All Hinges, Rollers, Locks – Lubricate — Repaired
- [x] Interior Trailer – Floor, Roof, and Side Walls — Repaired
- [x] Interior – Resecure Plywood as Needed — Repaired
- [x] DOT Inspected – Sticker Applied — Repaired
- [N/A] California BIT Inspected & Passed — Repaired

NOTES:

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	12	GMRT	100	RO Front	12	GMRT	100
	LI Front	16	BS		RI Front	11	BS	
2	LO Middle				RO Middle			
	LI Middle				RI Middle			
3	LO Rear	6	BS	100	RO Rear	10	GMRT	100
	LI Rear				RI Rear	10	BS	

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	5/8
	R Front	
2	L Middle	
	R Middle	
3	L Rear	6/8
	R Rear	

Hubo: 0

Engine Hrs:

Prot. Time:

Fuel 8ths:

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: [signature] (Inspector signature)

Inspection Date: 8/25

Print Name: Justin Hoseth

Company Name: L & W FLEET SERVICES