Equipment ID	VIN	Year	Manufacturer	Primary Plate
OTRT H10993	3H3V532KXSS123228	2025	HYUNDAI	ME 5308781

XTRA Lease DOT / BIT Inspection and PM Worksheet

Check Mark = OK X = Needs Further Attention R = Repaired N/A = Not Applicable

✓	Glad Hands & Rubber Grommets	Repaired		✓	Sub-Frame – Slide Rails and Crossmembers	Repaired	
✓	7-Way Electrical Plug	Repaired		✓	Aerodynamic Side Skirts	Repaired	
✓	Registration, Valid License Plate and sticker	Repaired		✓	Slider Mechanism & Locking Pins - Lubricate, Release, Re-engage	Repaired	
✓	Lights, Wiring and Splice Conditions	Repaired		✓	Proper Lubricant Level in each Wheel End - Fill if necessary	Repaired	
✓	Exterior Trailer - Body Condition and Coupling Device	Repaired		✓	Wheels - Check for Cracks / Tire Matching	Repaired	
✓	Corner Locking Devices	Repaired		✓	Tires - free of impermissible damage or wear	Repaired	
✓	Landing Gear Legs /Gear Box and Bracing - Lubricate & Cycle	Repaired		✓	Lugnuts – Torque to 450-500 ft/lbs – Set wrench to 500 ft/lbs	Repaired	
✓	Fuel Tank and Fuel System (Reefer)	Repaired		✓	Metal Flow-Thru Valve Stem Caps	Repaired	
✓	Air Brake System - Test for Leaks	Repaired		✓	Conspicuity Tape–Side Panels, Rear Doors, Headboards	Repaired	
✓	Dump Valve (Air Ride Only) - Testoperation and check for Leaks	Repaired		✓	Mudflaps, Brackets, and Rubber Dock Bumpers	Repaired	
✓	ABS System - Actuate	Repaired		✓	Rear Impact Guard	Repaired	
✓	Air Lines - Check for damage / wear / chaffing	Repaired		✓	Doors – Proper Operation	Repaired	
✓	Suspension Hangers	Repaired		✓	Door Hold Backs and Pull Handles - Present & Functional	Repaired	
✓	Air Tank and Mounting Brackets	Repaired		✓	All Hinges, Rollers, Locks – Lubricate	Repaired	
✓	Brakes - Drums / Linings /Air Chambers	Repaired		✓	Interior Trailer – Floor, Roof, and Side Walls	Repaired	
✓	Brakes – ADB / Rotors, Calipers, Pistons, Chambers, Pads	Repaired		✓	Interior – Resecure Plywood as Needed	Repaired	
✓	Slack Adjusters / S-cams / Brake adjustment – Lubricate & adjust	Repaired		✓	DOT Inspected – Sticker Applied	Repaired	
✓	Suspension / U-Bolts / Springs	Repaired		✓	California BIT Inspected & Passed	Repaired	
✓	Flatbed Winches – Lubricate and Cycle	Repaired			NOTES:		

TIRES (in 32nds)

Axle	Position	TD	Brand	PSI	Position	TD	Brand	PSI
1	LO Front	10	Yokohama	100	RO Front	10	Yokohama	100
	LI Front	10	Yokohama	100	RI Front	10	Yokohama	100
2	LO Middle		N/A	N/A	RO Middle		N/A	N/A
	LI Middle				RI Middle			
3	LO Rear	10	Yokohama	100	RO Rear	10	Yokohama	100
	LI Rear	10	Yokohama	100	RI Rear	10	Yokohama	100

Brakes (Drum in 8ths / ADB in mm)

Axle	Position	Depth
1	L Front	5
	R Front	5
2	L Middle	N/A
	R Middle	
3	L Rear	5
	R Rear	5

Hubo: 15968

Engine Hrs: _____

Prot. Time: _____

Fuel 8ths: _____

By signing and dating this form the inspector certifies (i) the accuracy and completeness of the inspection of this vehicle in compliance with all of the requirements of 49 C.F.R. Part 396, and (ii) that the vehicle has passed inspection in accordance with 49 C.F.R. Part 396.17.

Inspection conducted by: _____ (Inspector signature)

Inspection Date: 8-8-2025

Print Name: Dalton Hart

Company Name: XTRA Lease LLC