

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
	53144	3-25

MOTOR CARRIER OPERATOR <u>ICD Freight Inc</u>	INSPECTOR'S NAME (PRINT OR TYPE) <u>Trat Gaw</u>
ADDRESS <u>13202 W 98th St</u>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <u>Lenexa KS 66215-1359</u>	VEHICLE IDENTIFICATION (✓AND COMPLETE) <input checked="" type="checkbox"/> LIC. PLATE NO. <input type="checkbox"/> VIN <input type="checkbox"/> OTHER <u>644902</u>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE
<b>1. BRAKE SYSTEM</b>				g. Ball and Socket Joints			
a. Service Brakes	✓			h. Tie Rods and Drag Links	✓		
b. Parking Brake System	✓			i. Nuts	✓		
c. Brake Drums or Rotors	✓			j. Steering System	✓		
d. Brake Hose	✓			<b>8. SUSPENSION</b>			
e. Brake Tubing	✓			a. Axle Positioning Parts	✓		
f. Low Pressure Warning Device	✓			b. Spring Assembly	✓		
g. Tractor Protection Valve	✓			c. Torque, Radius or Tracking Components	✓		
h. Air Compressor	✓			<b>9. FRAME</b>			
i. Electric Brakes	✓			a. Frame Members	✓		
j. Hydraulic Brakes	✓			b. Tire and Wheel Clearance	✓		
k. Vacuum Systems	✓			c. Adjustable Axle Assemblies (Sliding Subframes)	✓		
l. Antilock Brake System	✓			<b>10. TIRES</b>			
m. Automatic Brake Adjusters	✓			a. Steer-Axle Tires	✓		
<b>2. COUPLING DEVICES</b>				b. All Other Tires	✓		
a. Fifth Wheels	✓			c. Speed-Restricted Tires	✓		
b. Pintle Hooks	✓			<b>11. WHEELS AND RIMS</b>			
c. Drawbar/Towbar Eye	✓			a. Lock or Side Ring	✓		
d. Drawbar/Towbar Tongue	✓			b. Wheels and Rims	✓		
e. Safety Devices	✓			c. Fasteners	✓		
f. Saddle-Mounts	✓			d. Welds	✓		
<b>3. EXHAUST SYSTEM</b>				<b>12. WINDSHIELD GLAZING</b>			
a. No leaks forward of/directly below the driver/sleeper compartment.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	✓		
b. Bus: No leaking/discharging in violation of standard.	✓			<b>13. WINDSHIELD WIPERS</b>			
c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.	✓		
<b>4. FUEL SYSTEM</b>				<b>14. MOTORCOACH SEATS</b>			
a. Visible leak.	✓			Any passenger seat that is not securely fastened to the vehicle structure.	✓		
b. Fuel tank filler cap missing.	✓			<b>15. REAR IMPACT GUARD</b>			
c. Fuel tank securely attached.	✓			In place, securely attached, proper size, proper placement (see 393.86).	✓		
<b>5. LIGHTING DEVICES</b>				<b>16. OTHER</b>			
All lighting devices and reflectors required by Section 393 shall be operable.	✓			List any other condition(s) which may prevent safe operation of this vehicle			
<b>6. SAFELOADING</b>							
a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓						
b. Front End Structure	✓						
c. Intermodal Container Securement Devices	✓						
<b>7. STEERING MECHANISM</b>							
a. Steering Wheel Free Play	✓						
b. Steering Column	✓						
c. Front Axle Beam/All Other Steering Components	✓						
d. Steering Gear Box	✓						
e. Pitman Arm	✓						
f. Power Steering	✓						

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, ✗ NEEDS REPAIR, NA ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.