Revised 01/22

RECORD OF ANNUAL INSPECTION

(49 CFR, 396.17-23)

Prepare Separate Report for Each Vehicle Inspected

643380

DATE: 5-27-25

COMPANY NAME	VEHICLE TYPE
ICO Freight Inc.	☐ Truck ☑ Tractor ☐ Trailer ☐ Converter Dolly
ADDRESS (Street): 13202 N 98th st	VEHICLE MAKE: KW MODEL: T680 YEAR: 2023
CITY: Lenexa, KS, 66215	VEHICLE IDENTIFICATION (Use One - Company No. State Tag No. or VIN): 1XK-YD49X-0-RJ326441
QUALIFIED INSPECTOR'S NAME *(Please Print)*: Dalton Land	ID No.: 25963

REPORT OF CONDITION

(For Detailed Information on Inspection Procedures See FMCSR Section 396, Appendix G.)

	OK	Repair
BRAKES		
Adjustment	✓	
Mechanical Components	✓	
Drum/Rotor	✓	
Hose/Tubing	✓	
Lining	✓	
Low Air Warning	✓	
Trailer Air Supply	✓	
Compressor	✓	
Parking Brakes	✓	
Other	—	
COUPLERS		
Fifth-Wheel & Mount	✓	
Pin/Upper Plate	—	
Pintle-Hook/Eye	—	
Safety Chain(s)	✓	
EXHAUST		
Leaks	✓	
Placement	✓	

	OK	Repair
LIGHTING		
Headlights	✓	
Tail/Stop	✓	
Clearance/Marker	✓	
Identification	✓	
Reflectors	✓	
Other	—	
CAB/BODY		
Access	✓	
Eqpt./Load Secure	✓	
Tie-Downs	—	
Headerboard	—	
Other	—	
STEERING		
Adjustment	✓	
Column/Gear	✓	
Axle	✓	
Linkage	✓	
Power Steering	✓	
Other	—	
REAR IMPACT GUARD		

	OK	Repair
FUEL SYSTEM		
Tank(s)	✓	
Lines	✓	
SUSPENSION		
Springs	✓	
Attachments	✓	
Sliders	—	
FRAME		
Members	✓	
Clearance	✓	
TIRES		
Tread	✓	
Inflation	✓	
Damage	✓	
Other	—	
WHEELS/RIMS		
Fasteners	✓	
Disc/Spoke	✓	
WINDSHIELD		
	✓	
WINDSHIELD WIPERS		
	✓	
MIRRORS		

Remarks

This vehicle has been inspected and repaired as needed to comply with 49 CFR Part 396, Appendix G.

Dalton Land — QUALIFIED INSPECTOR'S SIGNATURE

5-27-25 — DATE