

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
160621443	53172	10-4-25
INSPECTOR'S NAME (PRINT OR TYPE) EDWARD HELTZ		
THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19 <input checked="" type="checkbox"/> YES		
VEHICLE IDENTIFICATION (V AND COMPLETE)		
<input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER 1SSY53ED2R1363487		
INSPECTION AGENCY/LOCATION (OPTIONAL)		

MOTOR CARRIER OPERATOR JCD  
 ADDRESS  
13250 W 15th 98th St.  
 CITY, STATE, ZIP CODE  
LEWIS KS 66215  
 VEHICLE TYPE  TRACTOR  TRAILER  TRUCK  BUS  
 (OTHER)

## VEHICLE COMPONENTS INSPECTED

OK	REQUIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
/		<b>1. BRAKES</b>	/			<b>7. STEERING MECHANISM</b>
/		a. Service Brakes	/			a. Pitman Arm
/		b. Parking Brake System	/			f. Power Steering
/		c. Brake Drums or Rotors	/			g. Ball and Socket Joints
/		d. Brake Hoses	/			h. Tie Rods and Drag Links
/		e. Brake Tubing	/			i. Nuts
/		f. Low Pressure Warning Device	/			j. Steering System
/		g. Tractor Protection Valve	/			<b>8. SUSPENSION</b>
/		h. Air Compressor	/			a. Axle Positioning Parts
/		i. Electric Brakes	/			b. Spring Assembly
/		j. Hydraulic Brakes	/			c. Torque, Radius or Tracking Components
/		k. Vacuum Systems	/			<b>9. FRAME</b>
/		l. Antilock Brake System	/			a. Frame Members
/		m. Automatic Brake Adjusters	/			b. Tire and Wheel Clearance
/		<b>2. DRAWBAR DEVICES</b>	/			c. Adjustable Axle Assemblies (Sliding Subframes)
/		a. Fifth Wheels	/			<b>10. TIRES</b>
/		b. Pintle Hooks	/			a. Steer-Axle Tires
/		c. Drawbar/Towbar Eye	/			b. All Other Tires
/		d. Drawbar/Towbar Tongue	/			c. Speed Restricted Tires
/		e. Safety Devices	/			<b>11. WHEELS AND RIMS</b>
/		f. Saddle-Mounts	/			a. Lock or Slide Ring
/		<b>3. LEAKAGE SYSTEMS</b>	/			b. Wheels and Rims
/		a. No leaks forward of/directly below the driver/sleeper compartment.	/			c. Fasteners
/		b. Bus: No leaking/discharging in violation of standard.	/			d. Welds
/		c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	/			<b>12. WINDSHIELD GLAZING</b>
/		<b>4. FUEL SYSTEM</b>	/			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
/		a. No visible leak.	/			<b>13. WINDSHIELD WIPERS</b>
/		b. Fuel Tank Filler Cap	/			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
/		c. Fuel tank securely attached.	/			<b>14. MOTORCOACH SEATS</b>
/		<b>5. LIGHTING DEVICES</b>	/			Any passenger seat that is not securely fastened to the vehicle structure.
/		All lighting devices and reflectors required by Section 393 shall be operable.	/			<b>15. REAR IMPACT GUARD</b>
/		<b>6. SAFE LOADING</b>	/			In place, securely attached, proper size, proper placement (see 393.66).
/		a. Vehicle parts, load, dunnage, spare tire, etc., secured.	/			<b>16. OTHER</b>
/		b. Front End Structure	/			List any other condition(s) which may prevent safe operation of this vehicle.
/		c. Intermodal Container Securement Devices	/			
/		<b>7. STEERING MECHANISM</b>	/			
/		a. Steering Wheel Free Play	/			
/		b. Steering Column	/			
/		c. Front Axle Beams/All Other Steering Components	/			
/		d. Steering Gear Box	/			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: / OK X NEEDS REPAIR NA IF ITEMS DO NOT APPLY. REPAIRED DATE

**CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396**