



DATE: 2/11/2026
 LOCATION: 608 - McPherson, KS
 INSPECTOR: Austin Belote

DOT INSPECTION - Passed
 4008962718 - Trailer

MOTOR CARRIER OPERATOR: JCD FREIGHT INC	TRACTOR NUMBER:
ADDRESS: 13202 W 98th St	TRAILER NUMBER: 53181
CITY, STATE, ZIP CODE: Lenexa, KS 66215-1359	VIN NUMBER: 1gr1p0621rk620792
DRIVER NAME: Chris Barber	LICENSE PLATE: 702130 STATE: KS

VEHICLE COMPONENTS INSPECTED

1. BRAKE SYSTEM	
Pass	a. Service Brakes
Pass	b. Parking Brake System
Pass	c. Brake Drums or Rotors
Pass	d. Brake Hose
Pass	e. Brake Tubing
NA	i. Electric/Disc Brakes
NA	j. Hydraulic Brakes
Pass	l. Antilock Brake System
Pass	m. Automatic Brake Adjusters
2. COUPLING DEVICES	
Pass	a. Fifth Wheels
NA	b. Pintle Hooks
NA	c. Drawbar/Towbar Eye
NA	d. Drawbar/Towbar Tongue
Pass	e. Safety Devices
NA	f. Saddle-Mounts
3. EXHAUST SYSTEM	
NA	a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment
NA	b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3)
NA	c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle
4. FUEL SYSTEM	
NA	a. Visible leak
NA	b. Fuel tank filler cap missing
NA	c. Fuel tank securely attached

5. LIGHTING DEVICES	
Pass	All lighting devices and reflectors required by Section 393 shall be operable.
6. SAFE LOADING	
Pass	a. Part(s) of the vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway
Pass	b. Protection against shifting cargo
NA	c. Container securement devices on intermodal equipment
8. SUSPENSION	
Pass	a. Any U-bolt(s), spring hangers or other axle positioning part(s) cracked, broken, loose or missing, resulting in shifting of an axle from its normal position
Pass	b. Spring Assembly
Pass	c. Torque, Radius or Tracking Components
9. FRAME	
Pass	a. Frame Members
Pass	b. Tire and Wheel Clearance
Pass	c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES	
Pass	b. All other tires
11. WHEELS	
Pass	a. Lock or Side Ring
Pass	b. Wheels and Rims
Pass	c. Fasteners
NA	d. Welds
15. REAR IMPACT GUARD	
Pass	a. In place, securely attached, proper size, proper placement (see 393.86).

TIRE AND BRAKE MEASUREMENTS							
9	9	IN	10	7	IN	IN	IN
32NDS	32NDS	IN	32NDS	32NDS	IN	IN	IN
100	100	3/4	3/4	100	100	PSI	PSI
PSI	PSI	IN	IN	PSI	PSI		
BRAKE SHOE							
8	8	IN	8	10	IN	IN	IN
32NDS	32NDS	IN	32NDS	32NDS	IN	IN	IN
100	100	3/4	3/4	100	100	PSI	PSI
PSI	PSI	IN	IN	PSI	PSI		
BRAKE SHOE							

16. OTHER/GENERAL NOTES	
List any other condition(s) which may prevent safe operation of this vehicle	
Tractor Lube: No	

This inspection was completed according to terms for qualifications in accordance with 49CFR-396

Electronic Signature: Austin Belote