

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
160621444	53195	1-27-26

MOTOR CARRIER OPERATOR <u>ICD</u>	INSPECTOR'S NAME (PRINT OR TYPE) <u>EDWARD HEFLE</u>
ADDRESS <u>13202 WEST 98th ST.</u>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19 <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <u>LENEXA KS 66215</u>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <u>155V53206RL470187</u>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTOR AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

OK	NEED REPAIR	REPAIRED DATE	ITEM	OK	NEED REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKE SYSTEM</b>				<b>e. Pitman Arm</b>
/			a. Service Brakes				f. Power Steering
/			b. Parking Brake System				g. Ball and Socket Joints
/			c. Brake Drums or Rotors				h. Tie Rods and Drag Links
/			d. Brake Hose				i. Nuts
/			e. Brake Tubing				j. Steering System
/			f. Low Pressure Warning Device				<b>8. SUSPENSION</b>
/			g. Tractor Protection Valve				a. Axle Positioning Parts
/			h. Air Compressor				b. Spring Assembly
/			i. Electric Brakes				c. Torque, Radius or Tracking Components
/			j. Hydraulic Brakes				<b>9. FRAME</b>
/			k. Vacuum Systems				a. Frame Members
/			l. Antilock Brake System				b. Tire and Wheel Clearance
/			m. Automatic Brake Adjusters				c. Adjustable Axle Assemblies (Sliding Subframes)
			<b>2. COUPLING DEVICES</b>				<b>10. TIRES</b>
/			a. Fifth Wheels				a. Steer-Axle Tires
/			b. Pintle Hooks				b. All Other Tires
/			c. Drawbar/Towbar Eye				c. Speed Restricted Tires
/			d. Drawbar/Towbar Tongue				<b>11. WHEELS AND RIMS</b>
/			e. Safety Devices				a. Lock or Side Ring
/			f. Saddle-Mounts				b. Wheels and Rims
			<b>3. EXHAUST SYSTEM</b>				c. Fasteners
/			a. No leaks forward of/directly below the driver/sleeper compartment.				d. Welds
/			b. Bus: No leaking/discharging in violation of standard.				<b>12. WINDSHIELD GLAZING</b>
/			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			<b>4. FUEL SYSTEM</b>				<b>13. WINDSHIELD WIPERS</b>
/			a. No visible leak.				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
/			b. Fuel Tank Filler Cap				<b>14. MOTORCOACH SEATS</b>
/			c. Fuel tank securely attached.				Any passenger seat that is not securely fastened to the vehicle structure.
			<b>5. LIGHTING DEVICES</b>				<b>15. REAR IMPACT GUARD</b>
/			All lighting devices and reflectors required by Section 393 shall be operable.				In place, securely attached, proper size, proper placement (see 393.86).
			<b>6. SAFE LOADING</b>				<b>16. OTHER</b>
/			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				List any other condition(s) which may prevent safe operation of this vehicle.
/			b. Front End Structure				
/			c. Intermodal Container Securement Devices				
			<b>7. STEERING MECHANISM</b>				
/			a. Steering Wheel Free Play				
/			b. Steering Column				
/			c. Front Axle Beam/All Other Steering Components				
/			d. Steering Gear Box				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK x NEEDS REPAIR, NA IF ITEMS DO NOT APPLY. REPAIRED DATE

**CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396**