



DATE: 3/6/2026
 LOCATION: 940 - Oak Grove, MO
 INSPECTOR: Dustin Ogle

DOT INSPECTION— Passed
 4009159400 - Trailer

MOTOR CARRIER OPERATOR ICD FREIGHT INC	TRACTOR NUMBER:
ADDRESS : 13202 W 98th St	TRAILER NUMBER: 53193
CITY, STATE, ZIP CODE Lenexa, KS 66215-1359	VIN NUMBER: 1JJV532D2RL470185
DRIVER NAME : Melvin Artis	LICENSE PLATE: 713019 STATE: KS

VEHICLE COMPONENTS INSPECTED

Pass	a. Service Brakes
Pass	b. Parking Brake System
Pass	c. Brake Drums or Rotors
Pass	d. Brake Hose
Pass	e. Brake Tubing
NA	i. Electric/Disc Brakes
NA	j. Hydraulic Brakes
NA	l. Antilock Brake System
Pass	m. Automatic Brake Adjusters
NA	a. Fifth Wheels
NA	b. Pintle Hooks
NA	c. Drawbar/Towbar Eye
NA	d. Drawbar/Towbar Tongue
NA	e. Safety Devices
NA	f. Saddle-Mounts
NA	a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment
NA	b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3)
NA	c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle
Pass	a. Visible leak
Pass	b. Fuel tank filler cap missing
Pass	c. Fuel tank securely attached

5. LIGHTING DEVICES	
Pass	All lighting devices and reflectors required by Section 393 shall be operable.
6. SAFE LOADING	
Pass	a. Part(s) of the vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway
Pass	b. Protection against shifting cargo
Pass	c. Container securement devices on intermodal equipment
8. SUSPENSION	
Pass	a. Any U-bolt(s), spring hangers or other axle positioning part(s) cracked, broken, loose or missing, resulting in shifting of an axle from its normal position
Pass	b. Spring Assembly
Pass	c. Torque, Radius or Tracking Components
9. FRAME	
Pass	a. Frame Members
Pass	b. Tire and Wheel Clearance
Pass	c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES	
Pass	b. All other tires
11. WHEELS	
Pass	a. Lock or Side Ring
Pass	b. Wheels and Rims
Pass	c. Fasteners
Pass	d. Welds
15. REAR IMPACT GUARD	
Pass	a. In place, securely attached, proper size, proper placement (see 393.86).

TIRE AND BRAKE MEASUREMENTS					
12	13	1 3/8	1 3/8	10	12
32NDS	32NDS	IN	IN	32NDS	32NDS
100	100	13/16	13/16	100	100
PSI	PSI	IN	IN	PSI	PSI
BRAKE STROKE					
BRAKE SHOE					
13	11	1 1/4	1 3/8	12	13
32NDS	32NDS	IN	IN	32NDS	32NDS
100	100	13/16	13/16	100	100
PSI	PSI	IN	IN	PSI	PSI
BRAKE STROKE					
BRAKE SHOE					

16. OTHER/GENERAL NOTES

List any other condition(s) which may prevent safe operation of this vehicle

This inspection was completed according to terms for qualifications in accordance with 49CFR-396

Electronic Signature: Dustin Ogle

Tractor Lube: No