

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
1011	53196	3-30-26

MOTOR CARRIER OPERATOR ICD	INSPECTOR'S NAME (PRINT OR TYPE) EDWARD HEILE
ADDRESS 13202 WEST 98TH ST.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE LENEXA, KS 66215	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER RL 478090
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input checked="" type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTOR AGENCY/LOCATON (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEED REPAIR	REPAIRED DATE	ITEM	OK	NEED REPAIR	REPAIRED DATE	ITEM
/			1. BRAKE SYSTEM	/			e. Pitman Arm
/			a. Service Brakes	/			f. Power Steering
/			b. Parking Brake System	/			g. Ball and Socket Joints
/			c. Brake Drums or Rotors	/			h. Tie Rods and Drag Links
/			d. Brake Hose	/			i. Nuts
/			e. Brake Tubing	/			j. Steering System
/			f. Low Pressure Warning Device	/			8. SUSPENSION
/			g. Tractor Protection Valve	/			a. Axle Positioning Parts
/			h. Air Compressor	/			b. Spring Assembly
/			i. Electric Brakes	/			c. Torque, Radius or Tracking Components
/			j. Hydraulic Brakes	/			9. FRAME
/			k. Vacuum Systems	/			a. Frame Members
/			l. Antilock Brake System	/			b. Tire and Wheel Clearance
/			m. Automatic Brake Adjusters	/			c. Adjustable Axle Assemblies (Sliding Subframes)
/			2. COUPLING DEVICES	/			10. TIRES
/			a. Fifth Wheels	/			a. Steer-Axle Tires
/			b. Pintle Hooks	/			b. All Other Tires
/			c. Drawbar/Towbar Eye	/			c. Speed-Restricted Tires
/			d. Drawbar/Towbar Tongue	/			11. WHEELS AND RIMS
/			e. Safety Devices	/			a. Lock or Side Ring
/			f. Saddle-Mounts	/			b. Wheels and Rims
/			3. EXHAUST SYSTEM	/			c. Fasteners
/			a. No leaks forward of/directly below the driver/sleeper compartment.	/			d. Welds
/			b. Bus: No leaking/discharging in violation of standard.	/			12. WINDSHIELD GLAZING
/			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	/			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
/			4. FUEL SYSTEM	/			13. WINDSHIELD WIPERS
/			a. No visible leak.	/			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
/			b. Fuel Tank Filler Cap	/			14. MOTORCOACH SEATS
/			c. Fuel tank securely attached.	/			Any passenger seat that is not securely fastened to the vehicle structure.
/			5. LIGHTING DEVICES	/			15. REAR IMPACT GUARD
/			All lighting devices and reflectors required by Section 393 shall be operable.	/			In place, securely attached, proper size, proper placement (see 393.86).
/			6. SAFE LOADING	/			16. OTHER
/			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	/			List any other condition(s) which may prevent safe operation of this vehicle.
/			b. Front End Structure	/			
/			c. Intermodal Container Securement Devices	/			
/			7. STEERING MECHANISM	/			
/			a. Steering Wheel Free Play	/			
/			b. Steering Column	/			
/			c. Front Axle Beam/All Other Steering Components	/			
/			d. Steering Gear Box	/			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, ____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.