



# ANNUAL VEHICLE REPORT

MILEAGE	UNIT
165 773	82109
DATE	
	1 APR 26.

MOTOR CARRIER OPERATOR SUCCESS INTERNATIONAL INC.	INSPECTOR'S NAME (PRINT OR TYPE) JOHN BOERBE
ADDRESS 77 S. JAMES STREET.	VIN 1J5V532D6NL288497
CITY, STATE, ZIP CODE WCH 6640	INSPECTION LOCATION WCH 110

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
X			1. BRAKE SYSTEM	X			4. FUEL SYSTEM	X			9. FRAME
X			a. Service Brakes	X			a. Visible leak	X			a. Frame Members
X			b. Parking Brake System	X			b. Fuel tank filler cap missing	X			b. Tire and Wheel Clearance
X			c. Brake Drums or Rotors	X			c. Fuel tank securely attached	X			c. Adjustable Axle Assemblies (Siding Subframes)
X			d. Brake Hoses	X			5. LIGHTING DEVICES	X			10. TIRES
X			e. Brake Tubing	X			All lighting devices and reflectors required by Section 393 shall be operable.	X			a. Tires on any steering axle of a power unit.
X			f. Low Pressure Warning Device	X			6. SAFE LOADING	X			b. All other tires.
X			g. Tractor Protection Valve	X			a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.	X			11. WHEELS AND RIMS
X			h. Air Compressor	X			b. Protection against shifting cargo.	X			a. Lock or Side Ring.
X			i. Electric Brakes	X			7. STEERING MECHANISM	X			b. Wheels and Rims
X			j. Hydraulic Brakes	X			a. Steering Wheel Free Play	X			c. Fasteners
X			k. Vacuum Systems	X			b. Steering Column	X			d. Welds
X			2. COUPLING DEVICES	X			c. Front Axle Beam and All Steering Components Other Than Steering Column	X			12. WINDSHIELD GLAZING
X			a. Fifth Wheels <i>PLATE</i>	X			d. Steering Gear Box	X			Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions)
X			b. Pintle Hooks	X			e. Pitman Arm	X			13. WINDSHIELD WIPERS
X			c. Drawbar/Towbar Eye	X			f. Power Steering	X			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
X			d. Drawbar/Towbar Tongue	X			g. Ball and Socket Joints	X			List any other condition which may prevent safe operation of this vehicle.
X			e. Safety Devices	X			h. Tie Rods and Drag Links	X			
X			f. Saddle-Mounts	X			i. Nuts	X			
X			3. EXHAUST SYSTEM	X			j. Steering System	X			
X			a. Any exhaust system determined to be leaking at a point forward of or directly below the driver/sleeper compartment.	X			8. SUSPENSION	X			
X			b. A bus exhaust system leaking or discharging to the atmosphere in violation of standards (1), (2) or (3).	X			a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.	X			
X			c. No part of the exhaust system of any motor vehicle shall be so located as would be likely to result in burning, charring, or damaging the electrical wiring, the fuel supply, or any combustible part of the motor vehicle.	X			b. Spring Assembly	X			
X				X			c. Torque, Radius or Tracking Components.	X			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: X OK, O NEEDS REPAIR, NA IF ITEMS DO NOT APPLY. REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396: